

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21008328/VQF3E2

**Date:** 17/08/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100499635  
**Claimant Vehicle No :** GBE7526D **Insured Vehicle No :** SMS9128C  
Date of Loss: 06/08/2021 Nature of Claim: TP Claim No: 5430212459SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE7526D**  
Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2566545  
Reg. Date: 16/03/2016 (Man. Year: 2015) Chassis No: KDH2010182132  
Colour: Silver Odometer: 171599 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 106/104 8PR Rear Tyre Size: 106/104 8PR  
Front Left Side: Bluearth 4 mm Rear Left Side: Bluearth 4 mm  
Front Right Side: Bluearth 4 mm Rear Right Side: Bluearth 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 10/08/2021  
Date Inspected: 11/08/2021 Inspected At: Hock Eng Automobile Workshop (HQ)  
Blk 3012 Bedok Industrial  
Park E #01-2034  
Singapore 489978  
Estimated Period of Repair: 7.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$44,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
3	1		*REAR BUMPER STEP PANEL SUPPORT	Repair	0.00 F	*- F
4	1		*REVERSE SENSOR	Cut	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
7	1		*TAILGATE	Buckled / Dented	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*REAR BODY PANEL RH	Buckled	0.00 F	*- F
12	1		*REAR BODY PANEL INNER	Repair	0.00 F	*- F
13	1		*STICKER	Necessary	0.00 F	*- F
14	1		*REAR BODY PANEL AIR VENT	Distorted	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >