

ASS. REC. BY:

REF: C72/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SM 8 5812AYr Regn: 1Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hondac.c. 1496Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 15199

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI1332580Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modl: NI / S/Rlm / STD A/Rlm or _____Tyre Size: F: 215/60R16

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 8/8/21D.O.I. 10/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or None N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 CR1A not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

China
Vehin
10/8/21
LKK

08/08/2021

Owner: GRAVITY CAR LEASING PTE LTD

Not Authorised
11 Rps 8
Penny After Pain
5-7 days

ESTIMATE TO REPAIR HONDA VEZEL - SMZ5812A

1pc	rear tailgate	Ry	\$ 1,210.90	✓
1pc	rear tailgate "VEZEL" emble	m	\$ 55.10	✓
1pc	rear tailgate "HONDA" logo	m	\$ 58.50	✓
1set	rear tailgate windscreen moulding	m	\$ 181.00	✓
1pc	rear tailgate LH reflector	CM	\$ 381.50	✓
1pc	rear tailgate outer garnish	m	\$ 485.50	✓
1pc	rear tailgate outer garnish chrome	m	\$ 181.50	✓
1pc	rear tailgate inner lock	R	\$ 198.40	X
1pc	rear tailgate inner rubber	m	\$ 135.20	X
1pc	rear tailgate inner garnish		\$ 420.50	?
1pc	rear LH taillamp	CM	\$ 485.50	✓
1pc	rear LH side bumper	Bu	\$ 385.20	✓
1pc	rear bumper	Ry	\$ 986.30	✓
2pcs	rear bumper side retainer @\$24.80	M/DIT	\$ 49.60	4
1pc	rear bumper LH reflector	CM	\$ 85.20	✓
1pc	rear end panel		\$ 580.90	?
1pc	rear end panel inner garnish		\$ 250.20	?
1pc	rear end panel outer sensor		\$ 195.25	?
1pc	rear LH fender protector	Bu	\$ 195.20	✓
			\$ 6,521.45	
less 20%			\$ 1,304.29	
			\$ 5,217.16	
1set	rear reverse sensor	s.nett	\$ 280.00	2000N-
1set	rear number plate & casing	s.nett	\$ 50.00	X
remove & refix rear windscreen glass			\$ 120.00	✓
wiring			\$ 80.00	201
tuffkote			\$ 80.00	?
sealant			\$ 80.00	400N
spray painting			\$ 1,000.00	800L
labour charges			\$ 1,000.00	?
Total			\$ 7,907.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

