

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008338/R1ES3Q2
Date: 17/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMC3822E	Insured Vehicle No :	SMH9319B
Date of Loss:	09/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3822E	Engine No:	2NR5237770
Make & Model:	TOYOTA VIOS, 1.5 E CVT (A)	Chassis No:	MR2B23F3101132757
Reg. Date:	29/06/2018 (Man. Year: 2018)	Odometer:	51815 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,157.00	2,338.75	1,818.25	43.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,490.00	590.00	28.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,237.00	3,828.75	2,408.25	38.61
Approved Total (Overridden) (S\$)		3,050.00		

(S\$)	6,237.00	3,050.00	3,187.00	51.10
+ GST 7.00/7.00% (S\$)	436.59	213.50	223.09	51.10
Nett Amount (S\$)	6,673.59	3,263.50	3,410.09	51.10
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,970.95		
Global Sum Settlement (S\$)		3,970.00		

INSPECTION

Date of Assignment: 10/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57, Enterprise Hub
 Singapore 608581

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2021)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC3822E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	781.00 FL	*781.00 FL
2	2		*BOOT LID HINGE LH /RH	Serviceable	462.00 FL	*- FL
3	1		*BOOT LID LOGO BADGE	Necessary	62.00 FL	*62.00 FL
4	1		*BOOT LID EMBLEM VIOS	Necessary	52.00 FL	*52.00 FL
5	1		*BOOT LID EMBLEM G	Necessary	54.00 FL	*54.00 FL
6	1		*BOOT LID LOCK	Bent	379.00 FL	*249.00 FL
7	1		*REAR BUMPER	Deformed	381.00 FL	*381.00 FL
8	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	462.00 FL	*- FL
9	2		*TAIL LAMP LOWER BRACKET LH/RH	Serviceable	422.00 FL	*- FL
10	1		*REAR REINFORCEMENT	Bent	471.00 FL	*395.00 FL
11	1		*END PANEL	Bent	790.00 FL	*691.00 FL
12	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
13	2		*REAR REVERSE SENSOR LH/RH	Distorted	760.00 FS	*200.00 FS
14	1		*BOOT LID INSULATOR CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*REAR CAR PLATE WITH HOLDER	Scratched	35.00 FS	*35.00 FS
16	1		*END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,236.00	3,005.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,079.00	666.25
Total Parts (\$\$)	4,157.00	2,338.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	700.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	600.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	40.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
5	TO REMOVE AND REFIT REAR COMPARTMENT FITTING ,TRIMMINGS ,GARNISH AND ETC	New	100.00	60.00
6	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (S\$)			2,080.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >