

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008340/BVCN2**Date:** 29/09/2021**REFERENCE**

|                              |                                               |                             |                    |                                   |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00042682000 |                                   |
| <b>Claimant Vehicle No :</b> | SMW7430X                                      | <b>Insured Vehicle No :</b> | GBF4077Y           |                                   |
| Date of Loss:                | 05/08/2021                                    | Nature of Claim:            | TP                 | Claim No: SNM21D204362/C01/CHEESC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |  |             |                   |
|-----------------------------|-----------------------------------|--|-------------|-------------------|
| Reg No:                     | <b>SMW7430X</b>                   |  | Engine No:  | R16B25520543      |
| Make & Model:               | HONDA CIVIC, 1.3 EC8 (M)          |  | Chassis No: | MRHFC5650LT000391 |
| Reg. Date:                  | 08/12/2020 (Man. Year: 2020)      |  | Odometer:   | 14942 km          |
| Colour:                     | White                             |  |             |                   |
| Engine Capacity:            | 1597 cc                           |  |             |                   |
| Market Value/New Car Price: | N/A                               |  |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |  |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 215/55R16    | Rear Tyre Size:  | 215/55R16    |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>          | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                          | 14,225.52         | 8,029.84          | 6,195.68          | 43.55         |
| Miscellaneous Items            | 0.00              | 0.00              | 0.00              |               |
| Labour                         | 5,030.00          | 2,610.00          | 2,420.00          | 48.11         |
| Paintwork Labour               | 0.00              | 0.00              | 0.00              |               |
| Towing                         | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>      | <b>19,255.52</b>  | <b>10,639.84</b>  | <b>8,615.68</b>   | <b>44.74</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b> | <b>1,347.89</b>   | <b>744.79</b>     | <b>603.10</b>     | <b>44.74</b>  |
| <b>Nett Amount (\$\$)</b>      | <b>20,603.41</b>  | <b>11,384.63</b>  | <b>9,218.78</b>   | <b>44.74</b>  |

**INSPECTION**

|                             |            |               |                                |
|-----------------------------|------------|---------------|--------------------------------|
| Date of Assignment:         | 11/08/2021 |               | 160 SIN MING DR                |
| Date Inspected:             | 10/08/2021 | Inspected At: | #01-14 SIN MING AUTO CITY      |
|                             |            |               | SINGAPORE 575722               |
|                             |            |               | REPAIRER: TEAM AUTOPRO PTE LTD |
| Estimated Period of Repair: | 8.0 days   |               |                                |

**Adjuster:** Lim Teow Guan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 29 Sep 2021)             |
| <b>Parts:</b>        | 144                                                                                                                                                                          | HONDA CIVIC 1.3 EC8 (M) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMW7430X)                                                                                                                                    |                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                           |

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition                  | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------|----------------------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                               | Dented                     | 789.60 FL   | *789.60 FL   |
| 2   | 1   |          | *BOOTLID LOGO                          | Necessary                  | 69.50 FL    | *38.00 FL    |
| 3   | 1   |          | *BOOTLID EMBLEM CIVIC                  | Necessary                  | 98.00 FL    | *41.00 FL    |
| 4   | 1   |          | *BOOTLID EMBLEM I-VTEC                 | Necessary                  | 98.00 FL    | *42.00 FL    |
| 5   | 2   |          | *BOOTLID LAMP                          | Broken                     | 972.60 FL   | *901.60 FL   |
| 6   | 1   |          | *BOOTLID INNER LOCK                    | Jammed                     | 325.60 FL   | *195.30 FL   |
| 7   | 1   |          | *BOOTLID LOCK STRICKER                 | Not Damaged                | 68.20 FL    | *- FL        |
| 8   | 1   |          | *BOOTLID ANTENNA SENSOR                | Broken                     | 364.20 FL   | *180.00 FL   |
| 9   | 1   |          | *BOOTLID BUZZER                        | Broken                     | 148.00 FL   | *105.60 FL   |
| 10  | 1   |          | *BOOTLID INNER TRIM BOARD              | Not Damaged                | 304.60 FL   | *- FL        |
| 11  | 1   |          | *BOOTLID WEATHERSTRIP                  | Torn                       | 372.90 FL   | *144.20 FL   |
| 12  | 1   |          | *BOOTLID OUTER GARNISH                 | Broken                     | 348.60 FL   | *348.60 FL   |
| 13  | 1   |          | *BOOTLID NUMBER PLATE LAMP W/SWITCH    | Not Damaged                | 155.30 FL   | *- FL        |
| 14  | 2   |          | *BOOTLID HINGE                         | Bent                       | 304.00 FL   | *304.00 FL   |
| 15  | 1   |          | *BOOTLID REVERSE CAMERA                | Short Circuit              | 488.00 FL   | *280.00 FL   |
| 16  | 1   |          | *REAR BUMPER                           | Broken                     | 895.30 FL   | *631.20 FL   |
| 17  | 1   |          | *REAR BUMPER LOWER                     | Broken                     | 386.00 FL   | *258.50 FL   |
| 18  | 1   |          | *REAR BUMPER LOWER CHROME GARNISH      | Broken                     | 180.00 FL   | *180.00 FL   |
| 19  | 2   |          | *REAR BUMPER SIDE RETAINER             | Necessary                  | 159.60 FL   | *42.20 FL    |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT             | Bent                       | 190.80 FL   | *190.80 FL   |
| 21  | 2   |          | *REAR BUMPER BRACKET                   | Bent                       | 132.00 FL   | *70.00 FL    |
| 22  | 1   |          | *REAR BUMPER REFLECTOR                 | O/s Broken                 | 250.80 FL   | *85.50 FL    |
| 23  | 2   |          | *REAR BUMPER REFLECTOR GARNISH         | Broken                     | 421.80 FL   | *171.60 FL   |
| 24  | 1   |          | *REAR BUMPER REVERSE SENSOR<br>(4 Pcs) | Short Circuit (2 Pcs only) | 860.00 FL   | *430.00 FL   |
| 25  | 1   |          | *REAR END PANEL                        | Dented                     | 863.70 FL   | *595.80 FL   |
| 26  | 1   |          | *REAR END PANEL TOP GARNISH            | Broken                     | 208.60 FL   | *122.30 FL   |
| 27  | 1   |          | *SPARE TYRE PANEL                      | Repair                     | 736.90 FL   | *- FL        |
| 28  | 1   |          | *SPARE TYRE PANEL TOP BOARD            | Not Damaged                | 195.80 FL   | *- FL        |
| 29  | 1   |          | *SPARE TYRE TOOL TRAY                  | Not Damaged                | 155.90 FL   | *- FL        |
| 30  | 2   |          | *REAR FENDER                           | Cut                        | 1,936.20 FL | *1,936.20 FL |
| 31  | 2   |          | *REAR FENDER INNER TRIM BOARD          | Not Damaged                | 597.40 FL   | *- FL        |
| 32  | 2   |          | *TAILLAMP                              | Broken                     | 1,684.60 FL | *1,250.80 FL |
| 33  | 2   |          | *TAILLAMP BASE PANEL                   | Not Damaged                | 579.40 FL   | *- FL        |
| 34  | 1   |          | *SUNDRIES                              | Not Necessary              | 80.00 FS    | *- FS        |
| 35  | 1   |          | *BOOTLID SEALANT                       | Necessary                  | 100.00 FS   | *30.00 FS    |
| 36  | 1   |          | *BOOTLID INNER TRIM BOARD CLIPS        | Necessary                  | 50.00 FS    | *20.00 FS    |
| 37  | 1   |          | *BOOTLID OUTER GARNISH CLIPS           | Necessary                  | 50.00 FS    | *20.00 FS    |
| 38  | 1   |          | *REAR BUMPER CLIPS                     | Necessary                  | 50.00 FS    | *30.00 FS    |
| 39  | 1   |          | *REAR BUMPER LOWER CLIPS               | No such part               | 480.00 FS   | *- FS        |
| 40  | 2   |          | *REAR BUMPER REFLECTOR GARNISH CLIPS   | No such part               | 100.00 FS   | *- FS        |
| 41  | 4   |          | *REAR BUMPER REVERSE SENSOR SEAL       | Necessary                  | 192.00 FS   | *192.00 FS   |
| 42  | 1   |          | *REAR END PANEL SEALANT                | Necessary                  | 100.00 FS   | *40.00 FS    |
| 43  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS      | Necessary                  | 50.00 FS    | *20.00 FS    |
| 44  | 1   |          | *SPARE TYRE PANEL SEALANT              | Not Necessary              | 100.00 FS   | *- FS        |
| 45  | 2   |          | *REAR FENDER INNER TRIM BOARD CLIPS    | Necessary                  | 100.00 FS   | *40.00 FS    |

Report was unsubmitted during this print-out.

9/29/21, 10:18 AM

Adjuster Report

| No.                                          | Qty | Part No. | Particulars                  | Condition     | Repairer's                                          | Amount             |
|----------------------------------------------|-----|----------|------------------------------|---------------|-----------------------------------------------------|--------------------|
| 46                                           | 2   |          | *TAILLAMP CLIPS              | Necessary     | 100.00 FS                                           | *50.00 FS          |
| 47                                           | 2   |          | *TAILLAMP SEAL               | Necessary     | 120.00 FS                                           | *40.00 FS          |
| 48                                           | 2   |          | *TAILLAMP BASE PANEL SEALANT | Not Necessary | 200.00 FS                                           | *- FS              |
| 49                                           | 1   |          | *REAR NUMBER PLATE W/CASING  | Cut           | 80.00 FS                                            | *80.00 FS          |
| F=Franchise part. S=SpcNett. L=ListItemDisc. |     |          |                              |               |                                                     |                    |
|                                              |     |          |                              |               | Sub Total (\$\$)                                    | 17,293.90 9,896.80 |
|                                              |     |          |                              |               | - List Item Discount on L Items 20.00/20.00% (\$\$) | 3,068.38 1,866.96  |
|                                              |     |          |                              |               | Total Parts (\$\$)                                  | 14,225.52 8,029.84 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                |          |                 |                 |
| 1                               | R&R REAR BOOTLID COMPONENT     | New      | 150.00          | 80.00           |
| 2                               | R&R REAR BUMPER REVERSE SENSOR | New      | 100.00          | 60.00           |
| 3                               | R&R REVERSE CAMERA             | New      | 100.00          | 40.00           |
| 4                               | CHECK WIRING                   | New      | 100.00          | 30.00           |
| 5                               | UPHOLSTERY                     | New      | 300.00          | 0.00            |
| 6                               | CONDUCT WATER LEAKAGE TEST     | New      | 180.00          | 0.00            |
| 7                               | DIAGNOSTIC & RESET FAULT CODE  | New      | 300.00          | 120.00          |
| 8                               | PANEL BEATING                  | New      | 1,800.00        | 1,000.00        |
| 9                               | RUST PROOFING                  | New      | 200.00          | 80.00           |
| 10                              | SPRAY PAINTING                 | New      | 1,800.00        | 1,200.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                |          | <b>5,030.00</b> | <b>2,610.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >