



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200538

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 26/01/2022
Reference CC4/FCI21008342/Epa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 505R
Insured Veh. YN 5612G
Claim No. D21002202MFCV
Policy No.
Accident Date 29/07/2021
Inspection Date 11/08/2021

Description	Total
Survey Inspection	1,644.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less: Discount	-1,064.00
Subtotal	580.00
GST (7%)	40.60
Grand Total	620.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008342/Epa3q2 Date: 26/01/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 5612G	Veh. Inspected	SKQ 505R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21002202MFCV	Excess (\$)	0.00	
Assign From	NEO JIE SI	Assign Date	10/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE BOXSTER	c.c	2706	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WP0ZZZ98ZFK110174	Colour	RED	
Odometer	74430 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35Z R20	PIRELLI	5 mm	
L/H Front Tyre	265/35Z R20	PIRELLI	5 mm	
R/H Rear Tyre	265/35Z R20	PIRELLI	5 mm	
L/H Rear Tyre	265/35Z R20	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2021	Inspection Date	11/08/2021	
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE . SINGAPORE 729648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 505R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,752.00	1,752.00
1	RETAINING FRAME FOR LOWER SPOILER	CRUSHED	335.30	335.30
2	NUT	NECESSARY	3.80	3.80
1	EXHAUST TRIM	CUT	151.80	151.80
4	SENSOR PARK ASSIST	NOT NECESSARY	1,137.20	-
4	SENSOR GASKET	NECESSARY	21.20	21.20
1	REAR BUMPER RETAINER LH	NOT NECESSARY	216.60	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	216.60	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	560.20	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	560.20	-
1	HEAT PROTECTION CENTRE UPPER	NOT NECESSARY	299.20	-
1	HEAT PROTECTOR OUTER LEFT	NOT NECESSARY	343.70	-
1	HEAT PROTECTOR OUTER RIGHT	NOT NECESSARY	343.70	-
1	PROTECTOR FILM LH	NECESSARY	23.70	23.70
1	PROTECTOR FILM RH	NECESSARY	23.70	23.70
8	BUND RIVET	NECESSARY	8.80	8.80
1	REAR BUMPER LOWER SPOILER TRIM	CUT	228.60	228.60
1	SUPPORT BRACKET FOR CAMERA	NOT NECESSARY	24.40	-
1	ARM CAMERA	NOT NECESSARY	19.50	-
1	REAR BUMPER REINFORCEMENT	DENTED	714.60	714.60
1	TAILGATE	DENTED	2,417.80	2,417.80
1	HINGE LID REAR LEFT	NOT NECESSARY	125.10	-
1	HINGE LID REAR RIGHT	NOT NECESSARY	125.10	-
1	GAS-PRESSURE SPRING	NOT NECESSARY	112.60	-
1	SUPPORT BRACKET FOR CONTROL ELEMENT	NOT NECESSARY	17.80	-
1	ACTUATOR ELEMENT	NOT NECESSARY	117.00	-
1	BOWDEN CABLE	NOT NECESSARY	104.50	-
1	STRIKER LOCK	BENT	95.30	95.30
1	LOCK LOWER PART	NOT NECESSARY	411.90	-
1	REAR LID WEATHERSTRIP	CRUSHED	163.20	163.20
1	SPOILER UPPER PART	BROKEN	579.20	579.20

Report Ref No. CC4/FCI21008342/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPOILER LOWER PART	MISSING	516.20	516.20
1	DRIVING MECHANISM FOR SPOILER	BROKEN	1,612.90	1,612.90
1	HINGE FOR SPOILER LH	NOT NECESSARY	1,034.60	-
1	HINGE FOR SPOILER RH	NOT NECESSARY	1,034.60	-
1	LID COVER FOR SPOILER	NOT NECESSARY	52.60	-
1	WIRE SET FOR SPOILER	NOT NECESSARY	146.90	-
2	BRACKET SUPPORT FOR SPOILER	NOT NECESSARY	265.20	-
1	LOGO 'PORSCHE'	NECESSARY	209.90	209.90
1	LOGO 'BOXSTER'	NECESSARY	136.20	136.20
1	TAIL LIGHT LH	CUT	1,188.70	630.60
1	TAIL LIGHT RH	CUT	1,188.70	630.60
1	REAR FOR LIGHT	BROKEN	287.50	287.50
2	LICENSE PLATE LIGHT	BROKEN	188.60	188.60
1	ADDITIONAL BRAKE LIGHT	NOT NECESSARY	234.60	-
1	COVER TRIM FOR ADDITIONAL BRAKE LIGHT	NOT NECESSARY	499.80	-
1	ADHESIVE TAPE FOR ADDITIONAL LIGHT	NECESSARY	30.50	30.50
1	TAIL PIPE (CHROME)	CUT	1,571.20	1,351.30
2	(WF57) GASKET	NECESSARY	20.00	20.00
4	HEXAGON NUT (WF57)	NECESSARY	25.20	25.20
1	SUPPORT	BROKEN	800.30	800.30
2	CLAMP MUFFLER	NECESSARY	111.00	111.00
1	MAIN EXHAUST MUFFLER LH	DENTED	3,998.70	3,998.70
1	MAIN EXHAUST MUFFLER RH	DENTED	3,998.70	3,998.70
1	CLAMP	NECESSARY	94.60	94.60
1	FRONT BUMPER	DENTED	1,836.90	1,836.90
1	RETAINING FRAME LATERAL LH	NOT NECESSARY	64.80	-
1	RETAINING FRAME LATERAL RH	NOT NECESSARY	64.80	-
1	RETAINING FRAME CENTRE	NOT NECESSARY	176.80	-
1	DISC UPPER LH	NOT NECESSARY	59.80	-
1	DISC UPPER RH	BROKEN	59.80	59.80
1	DISC LOWER LH	NOT NECESSARY	59.80	-
1	DISC LOWER RH	NOT NECESSARY	59.80	-
1	COVER RETAINING FRAME LH	NOT NECESSARY	61.80	-

Report Ref No. CC4/FCI21008342/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER RETAINING FRAME RH	NOT NECESSARY	61.80	-
1	SPOILER LIP BLACK FRONT	NOT NECESSARY	424.90	-
8	RIVET	NECESSARY	20.80	20.80
1	RETAINING FOR ULTRASOUND SENSOR LH	NECESSARY	30.60	30.60
1	RETAINING FOR ULTRASOUND SENSOR RH	NECESSARY	30.60	30.60
2	SENSOR PARK ASSIST OUTER	NOT NECESSARY	428.20	-
2	SENSOR PARK ASSIST INNER	NOT NECESSARY	568.60	-
1	TRIM COVER FOR SENSOR LH	NOT NECESSARY	28.30	-
1	TRIM COVER FOR SENSOR RH	NOT NECESSARY	28.30	-
1	GASKET FOR SENSOR	NECESSARY	5.30	5.30
1	FRONT BUMPER SENSOR LH	NOT NECESSARY	23.90	-
1	FRONT BUMPER SENSOR RH	NOT NECESSARY	23.90	-
2	FIXING DEVICE	NECESSARY	47.60	47.60
1	NUMBER PLATE BRACKET	BROKEN	41.10	41.10
1	TEMPERATURE SENSOR -FRT BPR	NOT NECESSARY	77.60	-
1	BONNET LOCK	NOT NECESSARY	497.70	-
1	FRONT TOP PANEL	NOT NECESSARY	105.80	-
1	FRONT TOP END COVER	NOT NECESSARY	125.00	-
4	CLAMP CLIP	NOT NECESSARY	6.40	-
4	SPACER FOR CLIP	NOT NECESSARY	13.20	-
1	BUMPER REINFORCEMENT	NOT NECESSARY	1,194.90	-
2	REINFORCEMENT GASKET	NOT NECESSARY	16.00	-
1	BUMPER LOWER REINFORCEMENT	NOT NECESSARY	425.60	-
1	ADDITIONAL HEADLAMP (LH)	NOT NECESSARY	638.60	-
1	ADDITIONAL HEADLAMP (RH)	NOT NECESSARY	638.60	-
1	DIRECTION INDICATOR LIGHT (RH)	NOT NECESSARY	72.90	-
2	SEAT BELT	JAMMED	1,793.60	1,793.60
1	SEAT-BELT BUCKLE PASSENGER	NECESSARY	277.30	277.30
1	SEAT-BELT BUCKLE DRIVERS	NECESSARY	277.30	277.30
1	CONTROL UNIT ,AIRBAG	NECESSARY	1,725.10	1,725.10
2	FRONT SENSOR AIRBAG	NOT NECESSARY	501.80	-
2	SENSOR SIDE AIRBAG	NOT NECESSARY	501.80	-
1	FLOOR (ADDITIONAL)	DENTED	938.90	938.90

Report Ref No. CC4/FCI21008342/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TERMINAL PIECE (ADDITIONAL)	DENTED	676.00	676.00
55	BLIND RIVET (ADDITIONAL)	NECESSARY	308.00	308.00
20	LENS -HEAD SCREW (ADDITIONAL)	NECESSARY	44.00	44.00
2	ADHESIVE (ADDITIONAL)	NECESSARY	2,254.00	2,254.00
1	HEAT PROTECTION PLATE (ADDITIONAL)	DENTED	437.30	437.30
1	HEADLAMP (ADDITIONAL)	BROKEN	2,618.20	2,618.20
1	(WE72) START/STOP WARNING SIGNSTICKER (ADDITIONAL)	NECESSARY	72.00	72.00
3	GASKET (ADDITIONAL)	NECESSARY	29.70	29.70
			50,977.00	34,685.90
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REMOVE/REPLACE DAMAGED BODY PARTS (REAR PORTION) REAR BUMPER ,REAR LID,REAR BUMPER REINFORCEMENT,SPOILER & ALL ACCIDENT DAMAGE AREAS.TO REPAIR REAR END PANEL ,REAR FENDER RH ,& ALL AREAS AFFECTED BY THE ACCIDENT .		9,360.00	6,240.00
	TO REMOVE/REPLACE DAMAGED BODY PARTS (FRONT PORTION) FRONT BUMPER ,FRONT BUMPER REINFORCEMENT & ALL ACCIDENT DAMAGE PARTS.		3,120.00	1,560.00
	TO RESPRAY FRONT BUMPER ,REAR BUMPER ,REAR LID ,REAR END PANEL,REAR FENDER RH ,REAR UPPER SPOILER ,REAR FENDER LH.		8,500.00	7,550.00
	TO CARRY -OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION .		500.00	300.00
	TO SUPPLY FRONT & REAR LICENCE PLATE WITH CASING.		140.00	140.00
	TO REMOVE & REPLACE THE REAR EXHAUST ASSY .		1,560.00	1,560.00
	TO REMOVE & REPLACE THE AIR BAGS ,AIR BAG ECU AND SEAT BELTS.		1,560.00	1,560.00
	TO TRANSFER THE REAR SPOILER MECHANISM .		780.00	780.00
	TO TRANSFER THE FRONT & REAR SENSORS.		500.00	200.00

Report Ref No. CC4/FCI21008342/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY SPECIAL CERAMIC COATING (PRICE TO BE ADVISE). (NPA)	NOT NECESSARY	-	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		300.00	250.00
	TO REMOVE & REPLACE REAR FLOOR PANEL & REAR END PANEL. (ADDITIONAL)		9,360.00	7,800.00
	TO RESPRAY REAR FLOOR PANEL. (ADDITIONAL)		1,100.00	1,100.00
	TO SUPPLY REAR BOOT CHASSIS STICKER . (ADDITIONAL)		150.00	150.00
			38,030.00	30,090.00
GRAND TOTAL			89,057.00	64,795.90
RECOMMENDED COST OF REPAIRS				64,795.90

Report Ref No. CC4/FCI21008342/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 505R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 505R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

