

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008343/TQY3M4**Date:** 07/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700021412
Claimant Vehicle No :	SMK2636R	Insured Vehicle No :	GBG2301H
Date of Loss:	04/08/2021	Nature of Claim:	TP
		Claim No:	8295172237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2636R	Engine No:	M15A1356931
Make & Model:	SUZUKI SWIFT, 1.5 AT ABS AIRBAG 2WD (A)	Chassis No:	JSAEZC21S00428090
Reg. Date:	26/12/2008 (Man. Year: 2008)	Odometer:	167675 km
Colour:	Silver		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,819.29	848.69	5,970.60	87.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,030.00	2,200.00	68.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,049.29	1,878.69	8,170.60	81.31
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	10,049.29	1,500.00	8,549.29	85.07

INSPECTION

Date of Assignment:	10/08/2021		
Date Inspected:	10/08/2021	Inspected At:	TSL Auto Garage Synergy Building, Kaki Bukit #01-44 Singapore 417800
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	543.30 FL	*500.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Cracked	43.20 FL	*43.20 FL
3	1		*REAR TAILLAMP RH	Cut	321.30 FL	*287.90 FL
4	1		*REAR TAILLAMP LOWER BRAKET RH	Not Necessary	65.30 FL	*- FL
5	1		*REAR FENDER RH	Repair	412.60 FL	*- FL
6	1		*REAR FENDER INNER COWLING RH	Cut	120.30 FL	*120.30 FL
7	1		*REAR FENDER INNER GARNISH RH	Not Necessary	132.50 FL	*- FL
8	1		*REAR WHEEL HOUSE PANEL RH	Not Necessary	584.10 FL	*- FL
9	1		*REAR FENDER MUDFLAP RH	Not Necessary	78.60 FL	*- FL
10	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	458.60 FL	*- FL
11	1		*REAR FENDER AIR VENT RH	Not Necessary	78.60 FL	*- FL
12	1		*REAR AXLE	Not Necessary	1,645.30 FL	*- FL
13	1		*REAR SHOCK ABSORBER RH	Not Necessary	354.60 FL	*- FL
14	1		*REAR WHEEL HUP BEARING RH	Not Necessary	128.30 FL	*- FL
15	1		*REAR EXHAUST MUFFLER	Not Necessary	986.10 FL	*- FL
16	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	82.40 FL	*- FL
17	1		*REAR END PANEL	Not Necessary	387.60 FL	*- FL
18	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
19	1		*REAR FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*10.00 FS
20	1		*REAR FENDER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*REAR TAILLAMP CLIPS	Not Necessary	20.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*REAR BUMPER REVERSE SENSOR (OLD DAMAGE)	Not Necessary	250.00 FS	*- FS
24	1		*REAR SPORT RIM RH (OLD DAMAGE)	Not Necessary	480.00 FS	*- FS
25	1		*REAR TYRE RH	Not Necessary	280.00 FS	*- FS
26	1		*BRAKE FLUIDE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,782.70	991.40
- List Item Discount on L Items 15.00/15.00% (\$)	963.41	142.71
Total Parts (\$)	6,819.29	848.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,400.00	500.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	500.00
3	TO RUST PROOF / TUFF COAT ON REAR ACCIDENT AREAS	New	300.00	30.00
4	LABOUR FOR REMOVE & RENEW REAR AXLE / REAR RH SHOCK ABSORBER	New	300.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
6	WIRING CHECK	New	80.00	0.00
Gross Labour Cost (\$)			3,230.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >