

ASS. REC. BY: Taufik

REF:

CS/ALG 21008343/Tqfs.

ASSIGNMENT

2023 Dec.

2008 / Dec.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

\$10K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SMK 2636R.

Yr Regn: _____

2008 / Dec.

Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Suzuki Swift

c.c. 1490

Colour: _____

Silver

A/C: Insured / Std / NI / NA

Sp. Reading: _____

167675

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

SSAEZC 21300 * 428090.

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: _____

F: _____

195/60R15

R: _____

2-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

D.O.I. _____

10/2/21 2530pm.

Survey held at _____

TSL Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or _____

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Rep. Format: _____

Lump Sum / L.B. / ()

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON SUZUKI SWIFT

VEHICLE NO : SMK2636R

DATE : 10/08/2021

PARTS DESCRIPTION

LIST ITEMS

- 1 REAR BUMPER
- 2 REAR BUMPER SIDE RETAINER RH
- 3 REAR TAILLAMP RH
- 4 REAR TAILLAMP LOWER BRACKET RH
- 5 REAR FENDER RH
- 6 REAR FENDER INNER COWLING RH
- 7 REAR FENDER INNER GARNISH RH
- 8 REAR WHEEL HOUSE PANEL RH
- 9 REAR FENDER MUDFLAP RH
- 10 REAR FENDER INNER TRIM BOARD RH
- 11 REAR FENDER AIR VENT RH
- 12 REAR AXLE
- 13 REAR SHOCK ABSORBER RH
- 14 REAR WHEEL HUP BEARING RH
- 15 REAR EXHAUST MUFFLER
- 16 REAR EXHAUST MUFFLER RUBBER MOUNTING
- 17 REAR END PANEL

QTY	UNTIL PRICE	AMOUNT
1	\$543.30	\$543.30 ⁴⁵⁰ de
1	\$43.20	\$43.20 an
2	\$321.30	\$321.30 an ^{287.40} an
1	\$65.30	\$65.30 xnn
1	\$412.60	\$412.60 skxR
1	\$120.30	\$120.30 at
1	\$132.50	\$132.50 xnn
1	\$584.10	\$584.10 xnn
1	\$78.60	\$78.60 xnn
1	\$458.60	\$458.60 xnn
1	\$78.60	\$78.60 xnn
1	\$1,645.30	\$1,645.30 x
1	\$354.60	\$354.60 x
1	\$128.30	\$128.30 x
1	\$986.10	\$986.10 x
2	\$41.20	\$82.40 x
1	\$387.60	\$387.60 x

TOTAL :	901.40	\$6,381.50	\$6,422.70
LESS 15% :	766.19	\$957.23	\$963.41
TOTAL :		\$5,424.28	\$5,459.30

S/NETT ITEMS

- 1 REAR BUMPER CLIPS
- 2 REAR FENDER INNER COWLING CLIPS
- 3 REAR FENDER TRIM CLIPS
- 4 REAR TAILLAMP CLIPS
- 5 REAR END PANEL SEALANT
- 6 REAR BUMPER REVERSE SENSOR - old damage.
- 7 REAR SPORT RIM RH - old damage
- 8 REAR TYRE RH
- 9 BRAKE FLUIDE

1	\$80.00	\$80.00 30ne
1	\$60.00	\$60.00 10ne
1	\$50.00	\$50.00 x7
1	\$20.00	\$20.00 x
1	\$80.00	\$80.00 x
1	\$250.00	\$250.00 200xnn
1	\$480.00	\$480.00 4xnn
1	\$280.00	\$280.00 xnn
1	\$60.00	\$60.00 xnn

TOTAL :	\$1,360.00	\$1,360.00	40
---------	------------	------------	----

TOTAL SPARE PARTS :	\$6,784.28	\$6,819.30
---------------------	------------	------------

LABOUR DESCRIPTION

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 TO RUST PROOF / TUFF COAT ON REAR ACCIDENT AREAS
- 4 LABOUR FOR REMOVE & RENEW REAR AXLE / . REAR RH SHOCK ABSORBER
- 5 TO CONDUCT WHEEL ALIGNMENT
- 6 WIRING CHECK

AMOUNT

400 \$1,400.00 ~~700~~
 400 \$1,000.00 ~~600~~
 \$300.00 30
 \$300.00 / 50 X nn
 Report \$150.00 80 X nn
 \$80.00 30 X nn

TOTAL LABOUR :830. \$3,230.00**TOTAL PARTS AND LABOUR :**\$10,049.30

Taufan 97495749
 WP' 11/8/21 @ 240pm
 C/B Repair after repair
 Taufan E. Lohman
 06 days

766.19
 40
 830
 1636.19
 45 \$ 1300
 04 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: