

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008344/UTCN2**Date:** 27/09/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00010072101

Claimant Vehicle No : GBE2654A**Insured Vehicle No :** SMR3127A

Date of Loss: 04/08/2021

Nature of Claim: TP

Claim No: SNM21D204340/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBE2654A**

Make & Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD2559477

Reg. Date: 12/10/2015 (Man. Year: 2015)

Chassis No: JTFHT02P000179314

Colour: Silver

Odometer: 185879 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,514.52	11,488.81	7,025.71	37.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,900.00	3,540.00	2,360.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,414.52	15,028.81	9,385.71	38.44
Approved Total (Overridden) (\$\$)		12,000.00		
(\$\$)	24,414.52	12,000.00	12,414.52	50.85
+ GST 7.00/7.00% (\$\$)	1,709.02	840.00	869.02	50.85
Nett Amount (\$\$)	26,123.54	12,840.00	13,283.54	50.85

INSPECTION

Date of Assignment: 10/08/2021

Date Inspected: 10/08/2021 Inspected At:

LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Sep 2021)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE2654A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	2,162.70 FL	*2,150.00 FL
2	1		*TAIL GATE LOGO	Necessary	85.30 FL	*68.50 FL
3	1		*TAIL GATE LOCK	Dented/Jammed	509.10 FL	*275.00 FL
4	1		*TAIL GATE LOCK STRIKER	Not Necessary	144.20 FL	*- FL
5	1		*TAIL GATE INNER LOCK ACTUATOR	Jammed	280.60 FL	*280.60 FL
6	1		*TAIL GATE INNER TRIM BOARD	Torn	550.10 FL	*341.20 FL
7	2		*TAIL GATE DAMPER RH/LH	Not Necessary	508.20 FL	*- FL
8	1		*TAIL GATE RUBBER	Twisted	429.45 FL	*395.00 FL
9	2		*TAIL GATE SIDE STOPPER RH/LH	Not Necessary	97.20 FL	*- FL
10	1		*TAIL GATE OUTER GARNISH	Not Necessary	383.10 FL	*- FL
11	1		*TAIL GATE OUTER HANDLE	Not Necessary	260.35 FL	*- FL
12	1		*REAR WINDSCREEN MOULDING	No such part	260.15 FL	*- FL
13	1		*REAR BUMPER	Distorted	502.20 FL	*502.20 FL
14	2		*REAR BUMPER SIDE RETAINER RH/LH	Cracked	300.90 FL	*300.90 FL
15	1		*REAR CORNER PANEL O/S	Dented	160.45 FL	*160.45 FL
16	1		*REAR END PANEL	Badly Dented	509.10 FL	*509.10 FL
17	1		*REAR END PANEL (INNER)	Badly Dented	807.50 FL	*807.50 FL
18	1		*REAR END PANEL TOP MOULDING	Bent	269.55 FL	*205.10 FL
19	1		*REAR FLOOR PANEL	Repair	1,810.50 FL	*- FL
20	1		*REAR SPARE TYRE BRACKET	Bent	283.10 FL	*283.10 FL
21	2		*TAIL LAMP RH/LH	Cracked	630.20 FL	*630.20 FL
22	2		*TAIL LAMP LOWER GARNISH RH/LH	Repair	203.00 FL	*- FL
23	2		*REAR NUMBER PLATE LAMP	Not Necessary	152.20 FL	*- FL
24	1		*REAR EXHAUST BOX	Repair	582.70 FL	*- FL
25	3		*REAR EXHAUST BOX MOUNTING	Not Necessary	211.50 FL	*- FL
26	1		*BONNET	Dented/Bent	567.10 FL	*567.10 FL
27	1		*BONNET LOGO	Necessary	80.30 FL	*68.50 FL
28	1		*BONNET LOCK	Twisted	130.40 FL	*130.40 FL
29	1		*FRONT GRILLE ASSY	Cracked	429.10 FL	*429.10 FL
30	1		*FRONT BUMPER	Distorted	592.10 FL	*592.10 FL
31	1		*FRONT BUMPER GRILLE (TOP)	No such part	465.10 FL	*- FL
32	1		*FRONT BUMPER GRILLE (LOWER)	Cracked	289.10 FL	*289.10 FL
33	2		*FRONT BUMPER SIDE RETAINER RH/LH	Bent	280.60 FL	*280.60 FL
34	2		*FRONT BUMPER BRACKET RH/LH	Bent	231.00 FL	*231.00 FL
35	1		*FRONT BUMPER TOP BEAM	Bent	241.50 FL	*241.50 FL
36	1		*FRONT BUMPER REINFORCEMENT	Repair	477.70 FL	*- FL
37	1		*HEADLAMP RH/LH	O/s Cracked	1,561.00 FL	*780.50 FL
38	1		*HEADLAMP SUPPORT PANEL	Bent	567.10 FL	*567.10 FL
39	1		*BRACE PANEL	Bent	140.40 FL	*140.40 FL
40	1		*FRONT CORNER PANEL RH/LH	Not Necessary	288.70 FL	*- FL
41	1		*AIR CON CONDENSER	Punctured/Bent	1,410.50 FL	*1,410.50 FL
42	1		*INTERCOOLER	Not Necessary	1,514.10 FL	*- FL
43	1		*INTERCOOLER INTAKE DUCT	Not Necessary	182.60 FL	*- FL
44	1		*RADIATOR	Punctured	2,210.95 FL	*2,115.00 FL
45	1		*TAILGATE STICKER 70KM/H	Necessary	35.00 FS	*10.00 FS
46	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

9/27/21, 10:35 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
48	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
49	1		*SET REAR INNER TRIM CLIPS	Necessary	35.00 FS	*35.00 FS
50	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
51	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
52	1		*SET REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
53	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
54	1		*COOLANT	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	24,452.70
					15,176.75	
					- List Item Discount on L Items 25.00/25.00% (\$)	5,938.18
					3,687.94	
					Total Parts (\$)	18,514.52
					11,488.81	
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,000.00	1,750.00
2	TO APPLY UNDERCOATING	New	180.00	120.00
3	SPRAY PAINTING	New	2,000.00	1,400.00
4	TO CHECK WIRING	New	80.00	20.00
5	TO REMOVE & REFIX REAR WINDSCREEN	New	180.00	100.00
6	TO REMOVE & REPLACE REAR EXHAUST	New	180.00	0.00
7	TO REMOVE & REPLACE AIR CON CONDENSER & TOP UP GAS	New	180.00	100.00
8	TO REMOVE & REPLACE REVERSE SENSOR & TESTING	New	100.00	50.00
Gross Labour Cost (\$)			5,900.00	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >