

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008346/KQF3N2**Date:** 30/08/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29144394AT2

Claimant Vehicle No : GBH3247U**Insured Vehicle No :** SKS8647B

Date of Loss: 08/08/2021

Nature of Claim: TP Claim No: 637426

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH3247U**

Make & Model: NISSAN NV200, 1.5 (M)

Engine No: K9KE628D407511

Reg. Date: 23/04/2018 (Man. Year: 2017)

Chassis No: VSKYBAM20Z0155659

Colour: Metallic Grey

Odometer: 32455 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Goodyear 9 mm

Rear Left Side: Goodyear 2 mm

Front Right Side: Goodyear 9 mm

Rear Right Side: Goodyear 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,405.21	1,841.77	563.44	23.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,250.00	1,170.00	48.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,825.21	3,091.77	1,733.44	35.92
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	4,825.21	2,400.00	2,425.21	50.26

INSPECTION

Date of Assignment: 10/08/2021

Date Inspected: 12/08/2021 Inspected At:

Kang Auto Engineering Pte Ltd
160 Sin Ming Drive, #02-16, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Aug 2021)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH3247U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH CORNER PANEL	Repair	215.00 FL	*- FL
2	1		*FRONT DOOR (RH)	Bent	1,252.20 FL	*1,219.70 FL
3	1		*FRONT DOOR HINGE (RH)	Bent	40.00 FL	*40.00 FL
4	1		*FRONT RH FENDER	Bent	883.25 FL	*504.70 FL
5	1		*FRONT RH SIGNAL LAMP	Scratched	60.90 FL	*60.90 FL
6	1		*FRONT RH FENDER INNER SHIELD	Distorted	110.00 FL	*110.00 FL
7	1		*DOOR COMPANY STICKER	Necessary	20.00 FS	*20.00 FS
8	1		*FRONT RH TYRE RIM COVER	Dented	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,661.35	2,035.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	256.14	193.53
Total Parts (\$\$)	2,405.21	1,841.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & TRANSFER NEW DOOR	New	160.00	60.00
2	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANELS	New	200.00	30.00
3	TO PUTTY AND SPRAY PAINT	New	1,200.00	600.00
4	LABOUR CHARGES	New	800.00	500.00
5	WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (\$)			2,420.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >