

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009892/KBS3Q2-1
Date: 16/09/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKZ2997T	Insured Vehicle No :	SHC8735A
Date of Loss:	13/09/2020	Nature of Claim:	TP
		Claim No:	MCT20090185

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ2997T		
Make & Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Engine No:	PY20666271
Reg. Date:	18/01/2016 (Man. Year: 2015)	Chassis No:	JM6GJ1032G0221227
Colour:	Metallic Red	Odometer:	80877 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,008.80	3,355.20	653.60	16.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,650.00	630.00	27.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,288.80	5,005.20	1,283.60	20.41
Approved Total (Overridden) (S\$)		4,000.00		

(S\$)	6,288.80	4,000.00	2,288.80	36.39
+ GST 7.00/7.00% (S\$)	440.22	280.00	160.22	36.40
Nett Amount (S\$)	6,729.02	4,280.00	2,449.02	36.39
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
(S\$)		4,980.00		
Liabe Amount (50.00%) (S\$)		2,490.00		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 15/09/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2020)
Parts:	143	MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ2997T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FENDER	Bent	1,312.00 FL	*1,312.00 FL
2	1		*REAR LH FENDER QUARTER GLASS GARNISH	Serviceable	263.00 FL	*- FL
3	1		*REAR LH DOOR	Bent	1,314.00 FL	*1,314.00 FL
4	1		*REAR LH DOOR INNER LOCK	Repair	249.00 FL	*- FL
5	1		*REAR LH DOOR POWER WINDOW MOTOR	Serviceable	156.00 FL	*- FL
6	1		*REAR LH DOOR POWER WINDOW MOTOR REGULATOR	Serviceable	149.00 FL	*- FL
7	1		*REAR LH DOOR FRAME STICKER	Necessary	59.00 FL	*59.00 FL
8	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	118.00 FL	*118.00 FL
9	1		*REAR LH RIM 17	Dented	1,341.00 FL	*1,341.00 FL
10	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,001.00	4,184.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	992.20	828.80
Total Parts (\$\$)	4,008.80	3,355.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMP, REAR LH DOOR & ATTACHMENTS; TO CUT, WELD & RENEW REAR LH FENDER, KNOCKING & REPAIR REAR END PANEL, LH ROCKER PANEL & REALIGN BOOTLID THE SAME	New	900.00	700.00
3	PUTTY & RESPRAY REAR BUMPER, REAR LH FENDER, LH ROCKER PANEL, REAR LH DOOR, REAR END PANEL, ROOF PANEL & ALL AFFECTED AREAS	New	800.00	600.00
4	REMOVE & REFIX REAR LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING THE SAME	New	50.00	50.00
5	REMOVE & REFIX ROOF LINING TO FACILITATE REPAIR }	New	120.00	100.00
6	REMOVE & REFIX REAR SEAT, CARPET TO FACILITATE REPAIR }	New	150.00	0.00
7	REMOVE & REFIX REAR LH WHEEL, BALANCE & REALIGN THE SAME	New	50.00	20.00
8	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (S\$)			2,280.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >