

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008348/KTCN2**Date:** 14/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00109292001		
Claimant Vehicle No :	SCN7922J	Insured Vehicle No :	GBH9651X		
Date of Loss:	06/08/2021	Nature of Claim:	TP	Claim No:	SNM21D204368/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCN7922J		Engine No:	2ZR0D74390
Make & Model:	TOYOTA VOXY, 2.0(A)		Chassis No:	ZWR800389583
Reg. Date:	06/12/2019 (Man. Year: 2019)		Odometer:	123640 km
Colour:	Metallic Pearl White			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50ZR17	Rear Tyre Size:	225/50ZR17
Front Left Side:	Habilead 8 mm	Rear Left Side:	Habilead 8 mm
Front Right Side:	Habilead 8 mm	Rear Right Side:	Habilead 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,549.00	4,527.02	6,021.98	57.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	710.00	2,390.00	77.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,649.00	5,237.02	8,411.98	61.63
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	13,649.00	4,000.00	9,649.00	70.69
+ GST 7.00/7.00% (\$\$)	955.43	280.00	675.43	70.69
Nett Amount (\$\$)	14,604.43	4,280.00	10,324.43	70.69

INSPECTION

Date of Assignment:	12/08/2021		
Date Inspected:	11/08/2021	Inspected At:	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
Parts: M1-MPV	TOYOTA VOXY 2.0(A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCN7922J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Repair	1,129.00 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD O/S	Cracked	285.00 FL	*285.00 FL
3	1		*HEADLAMP O/S	Mtg Cracked	3,165.00 FL	*3,001.75 FL
4	1		*HEADLAMP LOWER BRACKET O/S	Serviceable	109.00 FL	*- FL
5	1		*FRONT BUMPER	Mtg Cracked	1,469.00 FL	*972.25 FL
6	1		*FRONT BUMPER UNDER COWLING	Serviceable	396.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	O/s Dented	228.00 FL	*114.00 FL
8	1		*FRONT BUMPER FOGLAMP O/S	Serviceable	487.00 FL	*- FL
9	1		*FRONT BUMPER FOGLAMP GARNISH O/S	Serviceable	266.00 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Serviceable	565.00 FL	*- FL
11	1		*RADIATOR GRILLE BRACKET	Repair	147.00 FL	*- FL
12	1		*FRONT SHOCK ABSORBER O/S	Bent	689.00 FL	*449.20 FL
13	1		*FRONT SHOCK ABSORBER MOUNTING O/S	Serviceable	195.00 FL	*- FL
14	1		*FRONT LOWER ARM O/S	Serviceable	487.00 FL	*- FL
15	1		*FRONT WHEEL KNUCKLE O/S	Bent	598.00 FL	*465.50 FL
16	1		*FRONT WHEEL BEARING O/S	Necessary	290.00 FL	*215.00 FL
17	1		*FRONT END LINK O/S	Serviceable	214.00 FL	*- FL
18	1		*HEADLAMP TOP SUPPORT O/S	Serviceable	215.00 FL	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Repair	677.00 FL	*- FL
20	1		*FRONT BUMPER IMPACT ABSORBER	Serviceable	189.00 FL	*- FL
21	1		*FRONT FENDER INNER TOP BRACKET O/S	Repair	159.00 FL	*- FL
22	1		*FRONT FENDER HYBRID EMBLEM O/S	Not Necessary	73.00 FL	*- FL
23	1		*WIPER WASHER TANK	Serviceable	267.00 FL	*- FL
24	1		*WIPER WASHER TANK MOTOR	Serviceable	313.00 FL	*- FL
25	1		*FRONT BUMPER CLIPS (12 Pcs)	Necessary	66.00 FS	*50.00 FS
26	8		*FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	44.00 FS	*- FS
27	1		*FRONT TYRE O/S	Serviceable	380.00 FS	*- FS
28	1		*FRONT ALLOY RIM O/S	Dented	550.00 FS	*350.00 FS
29	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,702.00	5,902.70
- List Item Discount on L Items 25.00/25.00% (\$)	3,153.00	1,375.68
Total Parts (\$)	10,549.00	4,527.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	250.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	TO REMOVE AND REFIT O/S FRONT TYRE & RIMS.TO PERFORM TYRE BALANCING	New	50.00	20.00
4	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	140.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	100.00	60.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	220.00
7	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			3,100.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >