

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008355/ATCN2**Date:** 20/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00011932101

Claimant Vehicle No : SLQ4543S **Insured Vehicle No :** GBH931Y

Date of Loss: 19/07/2021 Nature of Claim: TP Claim No: SNM21D204391/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ4543S**

Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27091031269694

Reg. Date: 11/07/2017 (Man. Year: 2017) Chassis No: WDD1173422N504233

Colour: White Odometer: 67635 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,407.20	8,689.10	19,718.10	69.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	1,400.00	4,310.00	75.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,117.20	10,089.10	24,028.10	70.43
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	34,117.20	8,000.00	26,117.20	76.55
+ GST 7.00/7.00% (S\$)	2,388.20	560.00	1,828.20	76.55
Nett Amount (S\$)	36,505.40	8,560.00	27,945.40	76.55

INSPECTION

Date of Assignment: 10/08/2021

Date Inspected: 10/08/2021 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2021)
Parts:	143	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ4543S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,712.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	485.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	1,376.00 FL	*1,376.00 FL
4	1		*FRONT BUMPER LOGO	Necessary	196.00 FL	*196.00 FL
5	1		*FRONT BUMPER LIP (BLACK)	Not Necessary	365.00 FL	*- FL
6	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	186.00 FL	*- FL
7	2		*FRONT BUMPER SENSOR RH	Damaged	600.00 FL	*250.00 FL
8	6		*FRONT BUMPER SENSOR HOLDER	Necessary	384.00 FL	*120.00 FL
9	1		*FRONT BUMPER CENTER BEAM (LOWER)	Not Necessary	256.00 FL	*- FL
10	1		*FRONT BUMPER UPPER BEAM	Not Necessary	260.00 FL	*- FL
11	2		*FRONT BUMPER UPPER BEAM SIDE SUPPORT	Not Necessary	184.00 FL	*- FL
12	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	79.00 FL	*79.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	251.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	758.00 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Not Necessary	217.00 FL	*- FL
16	1		*FRONT BUMPER TOP RUBBER	Not Necessary	78.00 FL	*- FL
17	1		*FRONT BUMPER BOTTOM COVER GARNISH	Not Necessary	288.00 FL	*- FL
18	1		*FRONT HEADLAMP (LED)	O/s Cracked	5,956.00 FL	*2,978.00 FL
19	1		*FRONT HEADLAMP LOWER PANEL LH	Not Necessary	172.00 FL	*- FL
20	1		*FRONT HEADLAMP LOWER PANEL SUPPORTLH	Not Necessary	321.00 FL	*- FL
21	1		*FRONT GRILLE WITH CHROME	Not Necessary	1,113.00 FL	*- FL
22	2		*FRONT GRILLE SIDE AIR GUARD	Not Necessary	156.00 FL	*- FL
23	1		*HORN	Not Necessary	195.00 FL	*- FL
24	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	165.00 FL	*- FL
25	1		*FRONT FENDER RH	O/s Dented	1,572.00 FL	*786.00 FL
26	1		*FRONT FENDER COWLING (FRONT) RH	Deformed	198.00 FL	*198.00 FL
27	1		*RADIATOR SUPPORT PANEL	Not Necessary	870.00 FL	*- FL
28	1		*FRONT KNUCKLE ARM	Bent	1,298.00 FL	*972.00 FL
29	1		*FRONT LOWER ARM	Bent	518.00 FL	*518.00 FL
30	2		*FRONT LOWER ARM BOSH	Not Necessary	216.00 FL	*- FL
31	1		*FRONT WHEEL BEARING CHROM WITH WHEEL HUB	Damaged	715.00 FL	*420.00 FL
32	1		*STEERING RACK AND PINION	Not Necessary	7,755.00 FL	*- FL
33	1		*FRONT ABSORBER RH	Bent	806.00 FL	*806.00 FL
34	1		*STABILIZER LINKAGE RH	Not Necessary	107.00 FL	*- FL
35	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
36	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
37	1		*SET FRONT BUMPER BOTTOM COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
38	1		*SET FRONT NUMBER PLATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
39	1		*SET FRONT FENDER COWLING CLIPS	Necessary	80.00 FS	*30.00 FS
40	1		*SET SUPPORT PANEL UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
41	1		*COOLANT	Not Necessary	180.00 FS	*- FS
42	1		*FRONT RH WHEEL	Cut	1,000.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,388.00	9,559.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,980.80	869.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$)	28,407.20
						8,689.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,200.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	100.00
7	RESET ABS LIGHT	New	500.00	0.00
8	FOUR WHEEL ALIGNMENT	New	180.00	80.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	1,200.00	220.00
10	REMOVE AND REFIX AND REPROGRAMMING STEERING RACK AND PINION	New	800.00	0.00
Gross Labour Cost (\$\$)			5,710.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >