

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008360/TGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210053542
Claimant Vehicle No :	SHC6894L	Insured Vehicle No :	SNA590S
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	2963191624SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6894L	Engine No:	D4FDEH313452
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5623095
Reg. Date:	30/09/2015 (Man. Year: 2015)	Odometer:	509563 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,913.80	3,504.10	2,409.70	40.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,220.00	1,030.00	45.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,163.80	4,724.10	3,439.70	42.13
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	8,163.80	3,750.00	4,413.80	54.07
+ GST 7.00/7.00% (S\$)	571.47	262.50	308.97	54.07
Nett Amount (S\$)	8,735.27	4,012.50	4,722.77	54.07
+ Loss of Use (6.0 x S\$40.00/day) (S\$)		240.00		
+ Car Rental (6.0 x S\$50.99/day) (S\$)		305.94		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,560.44		
Global Sum Settlement (S\$)		4,550.00		

INSPECTION

Date of Assignment:	10/08/2021		
Date Inspected:	11/08/2021	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,119.00 FL	*1,119.00 FL
2	1		*BOOT LID LOCK	Not Necessary	99.00 FL	*- FL
3	1		*BOOTLID STRIKER	Repair	21.00 FL	*- FL
4	1		*BOOTLID EMBLEM	Necessary	27.00 FL	*27.00 FL
5	1		*BOOTLID CRDI	Necessary	29.00 FL	*29.00 FL
6	1		*BOOT LID RUBBER WEATHERSTRIP	Not Necessary	96.00 FL	*- FL
7	1		*BOOT LID LOWER GARNISH	Repair	290.00 FL	*- FL
8	2		*BOOTLID HINGES	Not Necessary	132.00 FL	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	190.00 FL	*- FL
10	2		*REAR LICENSE LAMP	Not Necessary	60.00 FL	*- FL
11	1		*END PANEL	Repair	250.00 FL	*- FL
12	1		*END PANEL INNER GARNISH	Not Necessary	74.00 FL	*- FL
13	2		*N/S & O/S TAIL LAMP	Cracked	842.00 FL	*842.00 FL
14	1		*N/S & O/S REFLECTOR	O/S Not Necessary / N/SCracked	700.00 FL	*350.00 FL
15	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
16	1		*REAR BUMPER LOWER COVER	Deformed	206.00 FL	*206.00 FL
17	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Necessary	58.00 FL	*58.00 FL
18	1		*REAR BUMPER INNER SPONGE	Cracked	114.00 FL	*114.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
20	2		*REAR BUMPER STAY O/S & N/S	Bent	108.00 FL	*108.00 FL
21	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
22	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
23	2		*REAR BUMPER REFLECTOR N/S & O/S	Not Necessary	92.00 FL	*- FL
24	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
25	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
26	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	52.00 FS	*- FS
27	1		*SET BOOTLID LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
28	1		*SET BOOTLID STICKERS	Necessary	100.00 FS	*80.00 FS
29	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
30	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,502.00** **3,859.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 588.20 354.90

Total Parts (\$\$) **5,913.80** **3,504.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	60.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS TO HEAR/WELD ,CUT -OFF THE THE END PANEL ,INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC	New	950.00	500.00
4	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH ,REAR BUMPER END PANEL	New	800.00	600.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	30.00
Gross Labour Cost (\$\$)			2,250.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >