

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21008364/AEA3Q2

Date:

10/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070149572

Claimant Vehicle No : SLD3211A**Insured Vehicle No :**

SMV8037Y

Date of Loss: 07/08/2021

Nature of Claim:

TP

Claim No:

1857834162SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLD3211A**

Make & Model: AUDI Q5, 2.0 TFSI Quattro (180BHP) (A)

Engine No: CNC165528

Reg. Date: 13/06/2016 (Man. Year: 2016)

Chassis No: WAUZZZ8R1GA123912

Colour: White

Odometer: 80927 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,122.00	4,260.48	7,861.52	64.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,272.00	2,022.00	2,250.00	52.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,394.00	6,282.48	10,111.52	61.68
+ GST 7.00/7.00% (S\$)	1,147.58	439.77	707.81	61.68

Nett Amount (S\$)	17,541.58	6,722.25	10,819.33	61.68
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,994.25		

INSPECTION

Date of Assignment: 13/08/2021

Date Inspected: 13/08/2021

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,724.00 FS	*2,179.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	276.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Repair	624.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
5	1		*FRONT BUMPER REINFORCEMENT FOAM	Not Necessary	114.00 FS	*- FS
6	4		*FRONT BUMPER PULL STRAP	Not Necessary	206.00 FS	*- FS
7	1		*FRONT BUMPER SECURING STRIP -LH	Not Necessary	37.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Cut	351.00 FS	*280.80 FS
10	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	38.00 FS	*- FS
11	1		*FRONT REINFORCEMENT	Not Necessary	708.00 FS	*- FS
12	1		*FRONT REINFORCEMENT COVER	Not Necessary	65.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	60.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
16	1		*FRONT RADIATOR GRILLE	Cut	1,918.00 FS	*1,534.40 FS
17	1		*QUATTRO EMBLEM	Necessary	106.00 FS	*84.80 FS
18	1		*FRONT RADIATOR GRILLE STRIKER PLATE	Not Necessary	131.00 FS	*- FS
19	1		*HORN -LH	Not Necessary	201.00 FS	*- FS
20	1		*HORN BRACKET	Not Necessary	25.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	6.00 FS	*- FS
23	1		*FRONT HEADLIGHT MOUNTING -LH/RH	N/S Cracked	236.00 FS	*94.40 FS
24	1		*FRONT HEADLIGHT RETAINING PLATE	Not Necessary	78.00 FS	*- FS
25	1		*FRONT HEADLIGHT -LH	Not Necessary	2,721.00 FS	*- FS
26	1		*FRONT HEADLIGHT LIFT CYLINDER -LH	Not Necessary	204.00 FS	*- FS
27	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
28	1		*FRONT FOG LAMP -LH	Not Necessary	286.00 FS	*- FS
29	1		*RADIATOR AIR GRILLE -LH	Not Necessary	25.00 FS	*- FS
30	1		*RADIATOR UPPER COVER	Not Necessary	31.00 FS	*- FS
31	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Necessary	350.00 FS	*26.88 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**12,122.00****4,260.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS HORNS OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS RIENSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER	New	2,000.00	850.00
5	TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER) (NPA)	New	0.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,272.00	2,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >