

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21008373/EUF3N2**Date:** 22/11/2021**REFERENCE**

Insured/Claimant: SONIYA HITEN KAMDAR Policy No: 7210013338  
Date of Loss: 08/08/2021 Nature of Claim: OD Claim No: 6239565849SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMY825B**  
Make & Model: KIA SORENTO, 2.2 (A) Engine No: D4HELH251848  
Reg. Date: 15/02/2021 (Man. Year: 2020) Chassis No: KNARH81BVM5047714  
Colour: Blue Odometer: 15759 km  
Engine Capacity: 2151 cc  
Market Value/New Car Price: S\$189,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18  
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm  
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	43,371.17	35,879.17	7,492.00	17.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,850.00	9,510.00	1,340.00	12.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>54,221.17</b>	<b>45,389.17</b>	<b>8,832.00</b>	<b>16.29</b>
<b>- Excess (S\$)</b>	<b>3,300.00</b>	<b>3,300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>50,921.17</b>	<b>42,089.17</b>	<b>8,832.00</b>	<b>17.34</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,564.48</b>	<b>2,946.24</b>	<b>618.24</b>	<b>17.34</b>
<b>Nett Amount (S\$)</b>	<b>54,485.65</b>	<b>45,035.41</b>	<b>9,450.24</b>	<b>17.34</b>

**INSPECTION**

Date of Assignment: 11/08/2021  
Date Inspected: 11/08/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 15.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Broken	561.00 FL	*561.00 FL
2	1		*SKID PLATE-FR BUMPER	Cut	166.00 FL	*166.00 FL
3	1		*LIP-FR BUMPER	Cut	34.00 FL	*34.00 FL
4	1		*REINF ASSY-FR BUMPER,LH	Broken	11.00 FL	*11.00 FL
5	1		*REINF ASSY-FR BUMPER,RH	Broken	11.00 FL	*11.00 FL
6	1		*GRILLE-FRONT BUMPER	Broken	246.00 FL	*246.00 FL
7	1		*PIECE-BUMPER GRILLE	Broken	105.00 FL	*105.00 FL
8	1		*AIR DUCT-FR BUMPER,LH	Broken	28.00 FL	*28.00 FL
9	1		*AIR DUCT-FR BUMPER,RH	Broken	28.00 FL	*28.00 FL
10	1		*LAMP ASSY-FR FOG,RH	Broken	646.00 FL	*646.00 FL
11	1		*LAMP ASSY-FR FOG,LH	Broken	646.00 FL	*646.00 FL
12	1		*WIRING HARNESS-FR BUMPER	Torn	213.00 FL	*213.00 FL
13	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	117.00 FL	*117.00 FL
14	1		*STIFFENER ASSY-FR BUMPER LWR	Broken	102.00 FL	*102.00 FL
15	1		*BRACKET-FR BUMPER SIDE,LH	Broken	15.00 FL	*15.00 FL
16	1		*BRACKET-FR BUMPER SIDE,RH	Broken	15.00 FL	*15.00 FL
17	1		*GARNISH ASSY-RAD GRILLE,UPR	Broken	209.00 FL	*209.00 FL
18	1		*COVER-RADIATOR GRILLE UPR	Broken	107.00 FL	*107.00 FL
19	1		*GRILLE ASSY-RADIATOR	Broken	692.00 FL	*692.00 FL
20	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	27.00 FL	*27.00 FL
21	2		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	378.00 FL	*378.00 FL
22	2		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	342.00 FL	*342.00 FL
23	1		*GUARD ASSY-FRONT WHEEL,LH	Torn	76.00 FL	*76.00 FL
24	1		*GUARD ASSY-FRONT WHEEL,RH	Crushed	76.00 FL	*76.00 FL
25	1		*PANEL ASSY-HOOD	Dented	1,438.00 FL	*1,438.00 FL
26	1		*HINGE ASSY-HOOD,RH	Bent	62.00 FL	*62.00 FL
27	1		*HINGE ASSY-HOOD,LH	Bent	62.00 FL	*62.00 FL
28	1		*INSULATOR-FENDER RH	Not Necessary	31.00 FL	*- FL
29	1		*INSULATOR-FENDER LH	Not Necessary	31.00 FL	*- FL
30	1		*INSULATOR-FENDER UPPER,RH	Not Necessary	17.00 FL	*- FL
31	1		*INSULATOR-FENDER UPPER,LH	Not Necessary	17.00 FL	*- FL
32	1		*PANEL ASSY-FENDER,RH	Dented	702.00 FL	*702.00 FL
33	1		*PANEL ASSY-FENDER,LH	Dented	702.00 FL	*702.00 FL
34	1		*BEAM COMPLETE-FR BUMPER	Dented	674.00 FL	*674.00 FL
35	1		*CARRIER ASSY-FRONT END MODULE	Broken	661.00 FL	*661.00 FL
36	1		*LIFTER-HOOD	Not Necessary	60.00 FL	*- FL
37	1		*PAD-HOOD INSULATING	Crushed	172.00 FL	*172.00 FL
38	1		*LATCH ASSY-HOOD	Bent	105.00 FL	*105.00 FL
39	1		*TCU	Broken	1,303.00 FL	*1,303.00 FL
40	1		*LAMP ASSY-HEAD,RH	Broken	2,279.00 FL	*2,279.00 FL
41	1		*LAMP ASSY-HEAD,LH	Broken	2,279.00 FL	*2,279.00 FL
42	1		*PROTECTOR-WIRING	Not Necessary	17.00 FL	*- FL
43	1		*PROTECTOR-WIRING	Not Necessary	20.00 FL	*- FL
44	1		*BRACKET-WIRING MTG	Not Necessary	9.00 FL	*- FL
45	1		*COVER ASSY-COWL TOP	Cut	316.00 FL	*316.00 FL
46	1		*GLASS-WINDSHIELD	Broken	1,536.00 FL	*1,536.00 FL
47	1		*BRACKET-W/S MLDG MTG,LH	Necessary	35.00 FL	*35.00 FL
48	1		*BRACKET-W/S MLDG MTG,RH	Necessary	35.00 FL	*35.00 FL
49	1		*MOULDING-WINDSHIELD UPR	Necessary	21.00 FL	*21.00 FL
50	1		*GARNISH ASSY-RH	Crumpled	116.00 FL	*116.00 FL
51	1		*GARNISH ASSY-LH	Necessary	116.00 FL	*116.00 FL
52	1		*CONDENSER ASSY-COOLER	Dented	934.00 FL	*934.00 FL
53	1		*DAM-AIR	Broken	23.00 FL	*23.00 FL
54	1		*GUARD-AIR,RH	Broken	12.00 FL	*12.00 FL
55	1		*PIPE & TUBE ASSY	Not Necessary	785.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR ASSY	Dented	814.00 FL	*814.00 FL
57	1		*INSULATOR-RADIATOR MTG,LWR	Not Necessary	10.00 FL	*- FL
58	1		*BRACKET ASSY-RADIATOR MTG,UPR	Not Necessary	24.00 FL	*- FL
59	1		*HOSE ASSY-RADIATOR,UPR	Not Necessary	48.00 FL	*- FL
60	1		*HOSE ASSY-RADIATOR,LWR	Not Necessary	52.00 FL	*- FL
61	1		*HOSE	Not Necessary	27.00 FL	*- FL
62	1		*RESERVOIR & HOSE ASSY-RAD	Not Necessary	165.00 FL	*- FL
63	1		*HOSE ASSY-WATER	Not Necessary	27.00 FL	*- FL
64	1		*BLOWER ASSY	Broken	698.00 FL	*698.00 FL
65	1		*GUARD-AIR	Broken	64.00 FL	*64.00 FL
66	1		*SHIELD-AIR INTAKE	Not Necessary	27.00 FL	*- FL
67	1		*DUCT ASSY-AIR	Broken	45.00 FL	*45.00 FL
68	1		*DUCT ASSY-AIR	Broken	69.00 FL	*69.00 FL
69	1		*CLEANER ASSY-AIR	Broken	175.00 FL	*175.00 FL
70	1		*SENSOR ASSY-AIR FLOW	Not Necessary	276.00 FL	*- FL
71	1		*HOSE ASSY-AIR INTAKE	Not Necessary	158.00 FL	*- FL
72	1		*GUARD ASSY-AIR,LH	Broken	49.00 FL	*49.00 FL
73	1		*INTERCOOLER	Dented	943.00 FL	*943.00 FL
74	1		*HOSE-BYPASS	Not Necessary	68.00 FL	*- FL
75	1		*VALVE-BYPASS	Bent	797.00 FL	*139.00 FL
76	1		*HOSE-INTERCOOLER INLET	Not Necessary	184.00 FL	*- FL
77	1		*BRKT-I/C,UPR	Not Necessary	29.00 FL	*- FL
78	1		*RESONATOR	Not Necessary	396.00 FL	*- FL
79	1		*STARTER ASSY	Not Necessary	645.00 FL	*- FL
80	1		*MANIFOLD ASSY-INTAKE	Not Necessary	760.00 FL	*- FL
81	1		*ELECTRONIC CONTROL UNIT	Not Necessary	1,906.00 FL	*- FL
82	1		*PANEL ASSY-UNDER COVER	Not Necessary	339.00 FL	*- FL
83	1		*WHEEL ASSY-ALUMINIUM	Cut	799.00 FL	*799.00 FL
84	1		*CRASH PAD ASSY-MAIN	Broken	865.00 FL	*865.00 FL
85	1		*HEAD LINING ASSY	Crushed	1,536.00 FL	*1,536.00 FL
86	1		*MAP BOARD ASSY-FRT SEAT BACK,R	Not Necessary	216.00 FL	*- FL
87	2		*ADJUSTER ASSY-HEIGHT	Not Necessary	86.00 FL	*- FL
88	1		*S/BELT ASSY-FR RH	Jammed	471.00 FL	*471.00 FL
89	1		*S/BELT ASSY-FR LH	Jammed	471.00 FL	*471.00 FL
90	1		*BUCKLE ASSY-FR S/BELT,RH	Not Necessary	97.00 FL	*- FL
91	1		*BUCKLE ASSY-FR S/BELT,LH	Not Necessary	97.00 FL	*- FL
92	1		*BUZZER ASSY-PIEZO	Missing	68.00 FL	*68.00 FL
93	1		*SENSOR ASSY-A TYPE CRASH	Necessary	44.00 FL	*44.00 FL
94	1		*HORN ASSY-BURGLAR ALARM	Not Necessary	107.00 FL	-
95	1		*SENSOR ASSY-PRESS TYPE CRASH	Necessary	88.00 FL	*88.00 FL
96	1		*SENSOR ASSY-A TYPE CRASH	Necessary	48.00 FL	*48.00 FL
97	1		*MODULE ASSY-STRG WHEEL AIR BAG	Broken	1,383.00 FL	*1,383.00 FL
98	1		*AIR BAG ASSY-PASSENGER	Broken	1,278.00 FL	*1,278.00 FL
99	1		*CURTAIN AIR BAG MODULE,RH	Not Necessary	1,483.00 FL	*- FL
100	1		*CURTAIN AIR BAG MODULE,LH	Broken	1,483.00 FL	*1,483.00 FL
101	1		*SWITCH ASSY-MULTI FUNCTION	Not Necessary	468.00 FL	*- FL
102	1		*BRACKET,IU ADHESIVE	Necessary	26.00 FS	*26.00 FS
103	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS
104	1		*COOLER ASSY-OIL (Supplementary)	Dented	403.00 FL	*403.00 FL
105	1		*WIRING ASSY-FRT (Supplementary)	Broken	2,063.00 FL	*2,063.00 FL
106	1		*MOULDING-FRONT BUMPER,RH (Supplementary)	Broken	69.00 FL	*69.00 FL
107	1		*MOULDING-FRONT BUMPER,LH (Supplementary)	Cut	69.00 FL	*69.00 FL
108	1		*CLIPS (X10) (Supplementary)	Necessary	10.00 FL	*10.00 FL
109	1		*WIRING ASSY-FEM (Supplementary)	Torn	682.00 FL	*682.00 FL
110	1		*RESERVOIR & PUMP ASSY-WASHER (Supplementary)	Broken	190.00 FL	*190.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
111	1		*PNL ASSY-FNDR/APRON UPR OTR,RH (Supplementary)	Dented	87.00 FL	*87.00 FL
112	1		*HORN ASSY-HIGH PITCH (Supplementary)	Broken	75.00 FL	*75.00 FL
113	1		*BRACKET ASSY-FR BUMPER SD UPR (Supplementary)	Necessary	3.00 FL	*3.00 FL
114	1		*HORN ASSY-LOW PITCH (Supplementary)	Broken	75.00 FL	*75.00 FL
115	1		*GARNISH-FENDER SIDE UPR,RH (Supplementary)	Broken	97.00 FL	*97.00 FL
116	1		*GARNISH-FENDER SIDE UPR,LH (Supplementary)	Broken	97.00 FL	*97.00 FL
117	1		*GARNISH-FR DR RH (Supplementary)	Cut	117.00 FL	*117.00 FL
118	1		*GARNISH ASSY-FNDR SIDE,RH (Supplementary)	Broken	76.00 FL	*76.00 FL
119	1		*COVER-FENDER APRON UPR,RH (Supplementary)	Missing	8.00 FL	*8.00 FL
120	1		*COVER-FENDER APRON UPR,LH (Supplementary)	Missing	8.00 FL	*8.00 FL
121	1		*GUSSET-RADIATOR SUPPORT LWR,LH (Supplementary)	Necessary	14.00 FL	*14.00 FL
122	1		*GUSSET-RADIATOR SUPPORT LWR,RH (Supplementary)	Necessary	14.00 FL	*14.00 FL
123	1		*CLIPS (X4) (Supplementary)	Necessary	8.00 FL	*8.00 FL
124	1		*ARM COMPLETE-FR LWR,RH (Supplementary)	Bent	474.00 FL	*474.00 FL
125	1		*SENSOR ASSY-A TYPE CRASH (Supplementary)	Necessary	44.00 FL	*44.00 FL
126	1		*MODULE ASSY-AIR BAG CONTROL (Supplementary)	Necessary	860.00 FL	*860.00 FL
127	1		*S/BELT ASSY-2ND RH (Supplementary)	Jammed	377.00 FL	*377.00 FL
128	1		*S/BELT ASSY-2ND LH (Supplementary)	Jammed	377.00 FL	*377.00 FL
129	1		*BACK ASSY-FR SEAT,RH (Supplementary)	Broken	3,167.00 FL	*3,167.00 FL
130	1		*BACK ASSY-FR SEAT,LH (Supplementary)	Broken	2,287.00 FL	*2,287.00 FL
131	1		*CONTACT ASSY-CLOCK SPRING (Supplementary)	Necessary	217.00 FL	*217.00 FL
132	1		*ANTIFREEZER (X2) (Supplementary)	Necessary	217.96 FL	*217.96 FL
133	1		*HOSE-COOLER (Supplementary)	Torn	18.00 FL	*18.00 FL
134	1		*COVER ASSY-VALVE BODY (Supplementary)	Dented	159.00 FL	*159.00 FL
135	1		*OIL-TRANSMISSION (X4) (Supplementary)	Necessary	472.00 FL	*472.00 FL
136	1		*STRUT ASSY-FR RH (Supplementary)	Bent	419.00 FL	*419.00 FL
137	1		*VALVE-TPMS (Supplementary)	Broken	159.00 FL	*159.00 FL
138	1		*CROSSMEMBER COMPL (Supplementary)	Bent	1,402.00 FL	*1,402.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>54,194.96</b>	<b>44,834.96</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	10,823.79	8,955.79
<b>Total Parts (S\$)</b>	<b>43,371.17</b>	<b>35,879.17</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER,BONNET,FRT SUPPORT PANEL,FRT FENDER RH & LH.REPAIR FRT DOOR RH & LH	New	2,400.00	2,200.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
6	SPRAY PAINT FOR FRT BUMPER,BONNET,FRT FENDER RH & LH,FRT SUPPORT,FRT DOOR RH & LH	New	3,040.00	2,100.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
9	RENEW FRT DASHBOARD	New	400.00	400.00
10	RENEW FRT AIRBAG AND SET BELTS	New	400.00	400.00
11	REMOVE & INSTALL FRT RIGHT & LEFT SEATS AND SEAT AIRBAG	New	400.00	400.00
12	REMOVE & INSTALL ROOF LINING	New	400.00	200.00
13	RENEW FRT WINDSCREEN	New	240.00	240.00
14	TRANSFER FRT RIGHT RIM	New	30.00	30.00
15	APPLY SOLAR FILM FOR FRT WINDSCREEN	New	220.00	220.00
16	APPLY SEALANT FOR FRT WINDSCREEN	New	80.00	80.00
17	REPLACE RH WHEEL HOUSING OUTER,REPAIR RH WHEEL HOUSING INNER,LH WHEEL HOUSING LH & RH FRONT CHASSIS (Supplementary)	New	1,200.00	1,200.00
18	RESPRAY ON ;H & RH WHEEL HOUSING LH & RH CHASSIS (Supplementary)	New	700.00	700.00
19	REPLACE FRONT WIRE (Supplementary)	New	400.00	400.00
20	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT (Supplementary)	New	120.00	120.00
21	REPLACE FRONT UNDERCARRIAGE PARTS (Supplementary)	New	400.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,850.00</b>	<b>9,510.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**