

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21008374/T1TF3N2**Date:** 23/08/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000099	
Claimant Vehicle No :	SHA3792C	Insured Vehicle No :	SMH9241R	
Date of Loss:	29/03/2021	Nature of Claim:	TP	Claim No: M2101593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3792C	Engine No:	D4FDGU613764
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU087874
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,785.38	0.00	3,785.38	100.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,560.00	660.00	900.00	57.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,356.38	671.00	4,685.38	87.47
+ GST 7.00/7.00% (S\$)	374.95	46.97	327.98	87.47
Nett Amount (S\$)	5,731.33	717.97	5,013.36	87.47

INSPECTION

Date of Assignment:	11/08/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	10/08/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3792C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID (Not Necessary)	Old Damaged	2,609.80 FL	-	*- FL
2	1		*BOOTLID H EMBLEM (Not Necessary)	Old Damaged	63.10 FL	-	*- FL
3	1		*BOOTLID CRDI EMBLEM (Not Necessary)	Old Damaged	52.40 FL	-	*- FL
4	1		*BOOTLID I40 EMBLEM (Not Necessary)	Old Damaged	67.90 FL	-	*- FL
5	1		*REAR BUMPER	Repair	1,106.00 FL	-	*- FL
6	1		*REAR BUMPER UNDER COVER	Repair	228.00 FL	-	*- FL
7	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
8	1		*BOOTLID COMFORTDELGRO	Not Necessary	15.00 F	-	*- F
9	1		*BOOTLID 65521111	Not Necessary	15.00 F	-	*- F
10	1		*REAR BUMPER MAT	Not Necessary	50.00 F	-	*- F
11	1		*REVERSE SENSORS	Not Necessary	135.70 F	-	*- F
12	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	-	*- FL
13	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	-	*- FL
					Sub Total (\$\$)	4,677.80	0.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	892.42	0.00
					Total Parts (\$\$)	3,785.38	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	600.00	250.00
3	TUFF KOTE	New	50.00	0.00
4	CHECK LIGHTINGS ETC	New	40.00	0.00
5	R/I REVERSE SENSORS	New	120.00	30.00
6	TOWING FEE - KING DOLLY	New	150.00	100.00
Gross Labour Cost (\$\$)			1,560.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >