MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

ehicle No.: SH6621B

Make : HYUNDAI

Model : IONIQ(G2) Date: 10/08/21

Insurance: NTUC

P/P.

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	REAR BUMPER COVER	75	1	W \$459.40
10	REAR BUMPER CLIPS			19(- \$22.00
f	REAR BUMPER CENTRE MOULDING ASSY	l		de -\$451.25
4	REAR BUMPER REINFORCEMENT			\$ \$394.80
*	FOG LAMP			\$201.50
2	RR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	
1	REAR BUMPER LICENCE LAMP			X \$85.30
			932.65	
	SUB TOTAL		1 1 12	\$1,890.45
	LESS 20%	,	1746,12.	\$378.09
	DISCOUNTED TOTAL		•	\$1,512.36
1	REAR BUMPER RUBBER MAT			¥ \$50.00
1	REAR NUMBER PLATE WITH TRIM COVER		-10%	au \$15.00
	REAR BUMPER REVERSE SENSOR		225 -10%	\$180.00
		1	225 -10% 1. 202,50 -10% 50	\$275.00
		Ų	1. 20	Ψ273.00
	Labour Charge		252.50.	
4	PANEL BEATING		2)2	350 \$700.00
	SPRAY PAINTING CHARGE			250 \$300.00
1	WIRING CHARGE		620. 1	N × \$50.00
ļi	REMOVE/REFIX REVERSE SENSOR		0 70	30.00
		ų.	man de la	\$60.00
Ì	TOTAL LABOUR		9 1628 200	\$1,130.00
	ESTIMATE TOTAL		630. 1 4 1628 -62 * 2 day	***
	- STATE TO TAL		~ /	\$2,917.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylor 9779595 wp, 6/8/2103pm plp resum new parts furlin c/marpoon 62 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: