

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6621B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	FOG LAMP	NOT NECESSARY	201.50	-
2	RR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER LICENCE LAMP	NOT NECESSARY	85.30	-
	LESS 20% DISCOUNT		-378.09	-186.53
			1,512.36	746.12
	NETT ITEMS			
1	REAR NUMBER PLATE WITH TRIM COVER (N)	CRACKED	45.00	45.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-22.50
			225.00	202.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,130.00	630.00
	GRAND TOTAL		2,917.36	1,628.62





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,628.62
---	--	----------

Report Ref No. NS/INC21008379/T1ucn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser