



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM21008380/Vqce2

8 SHENTON WAY #24-01

Date: 17/08/2021

AXA TOWERSINGAPORE 068811

ATTN: LOH CYNTHIA

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|---------------------|-------------|-----------------------|------------|
| Insured Veh. | SJV 694M | Veh. Inspected | SKW 5606T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | S1M03F99 | Excess (\$) | 0.00 |
| Assign From | LOH CYNTHIA | Assign Date | 11/08/2021 |

2. Vehicle Particulars & Condition


| | | | |
|-------------------------|-------------------|---------------------|--------------------|
| Make & Model | SUBARU XV 1.6 | c.c | 1600 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | JF1GP3KC5FG158490 | Colour | GREY |
| Odometer | 193006 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|--------|---------|
| R/H Front Tyre | 225/55 R17 | FALKEN | 6 mm |
| L/H Front Tyre | 225/55 R17 | FALKEN | 6 mm |
| R/H Rear Tyre | 225/55 R17 | FALKEN | 6 mm |
| L/H Rear Tyre | 225/55 R17 | FALKEN | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

| | | | |
|-----------------------|---|----------------------------|-------------------------|
| Accident Date | 08/08/2021 | Inspect Date / Time | 11/08/2021 (12:30 PM) |
| Survey held at | GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 | | |

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

| | |
|--|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|--|-----------------------|

Report Ref No. CS3/ASM21008380/Vqce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.