

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008382/TVCQ2
Date: 16/03/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00006492101
Claimant Vehicle No :	SKJ6880D	Insured Vehicle No :	SKP6679M
Date of Loss:	05/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204378/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ6880D	Engine No:	CAXD42575
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)	Chassis No:	WVWZZZ16ZDM079418
Reg. Date:	16/05/2014 (Man. Year: 2013)	Odometer:	335344 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,258.30	2,671.50	9,586.80	78.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,640.00	1,620.00	49.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,518.30	4,311.50	11,206.80	72.22
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	15,518.30	3,400.00	12,118.30	78.09
+ GST 7.00/7.00% (S\$)	1,086.28	238.00	848.28	78.09
Nett Amount (S\$)	16,604.58	3,638.00	12,966.58	78.09

INSPECTION

Date of Assignment:	10/08/2021		
Date Inspected:	12/08/2021	Inspected At:	AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2022)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ6880D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Not Necessary	1,120.00 FL	*- FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	22.54 FL	*- FL
3	1		*FRONT BUMPER	Deformed	1,274.00 FL	*920.00 FL
4	1		*FRONT BUMPER RETAINER RH	Not Necessary	262.00 FL	*- FL
5	1		*FRONT BUMPER GRILLE	Not Necessary	783.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	219.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP GRILLE RH	Not Necessary	204.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	796.00 FL	*- FL
9	1		*FRONT FENDER RH	Bent	674.00 FL	*460.00 FL
10	1		*FRONT FENDER COWLING RH	Not Necessary	320.00 FL	*- FL
11	1		*FRONT DOOR RH	Repair	1,481.00 FL	*- FL
12	2		*FRONT DOOR HINGE TOP AND BOTTOM RH	Not Necessary	364.00 FL	*- FL
13	1		*FRONT DOOR CHECKER RH	Not Necessary	187.00 FL	*- FL
14	1		*FRONT DOOR INNER TRIM RH	Not Necessary	1,041.00 FL	*- FL
15	1		*FRONT RIM RH	Cut	950.00 FL	*780.00 FL
16	1		*FRONT ABSORBER RH	Not Necessary	419.00 FL	*- FL
17	1		*FRONT LOWER ARM RH	Not Necessary	713.00 FL	*- FL
18	1		*FRONT KNUCKLE RH	Bent	622.90 FL	*425.00 FL
19	1		*FRONT KNUCKLE BEARING RH	Bent	420.00 FL	*350.00 FL
20	1		*FRONT BEARING HUB RH	Not Necessary	459.00 FL	*- FL
21	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
22	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	120.00 FS	*- FS
23	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	120.00 FS	*- FS
24	1		*FRONT TYRE RH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,491.44	2,965.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,233.14	293.50
Total Parts (\$\$)	12,258.30	2,671.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	120.00	30.00
4	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	120.00	80.00
5	TO RNR UNDERCARRIAGE	New	250.00	100.00
6	TO CHECK WHEEL BALANCING	New	120.00	30.00
7	TO RNR REAR FRONT DOOR MECHANISM	New	250.00	0.00
Gross Labour Cost (\$\$)			3,260.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >