

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008383/BVCN2**Date:** 24/08/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00031812102		
Claimant Vehicle No :	SMJ6209U	Insured Vehicle No :	GY5566L		
Date of Loss:	07/08/2021	Nature of Claim:	TP	Claim No:	SNM21D204395/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6209U	Engine No:	LEB5616008
Make & Model:	HONDA FREED HYBRID, 1.5 (A)	Chassis No:	GB71079797
Reg. Date:	13/03/2019 (Man. Year: 2018)	Odometer:	176139 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	SUNWIDE 5 mm	Rear Left Side:	SUNWIDE 5 mm
Front Right Side:	SUNWIDE 5 mm	Rear Right Side:	SUNWIDE 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,451.20	5,258.00	7,193.20	57.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,740.00	2,260.00	56.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,451.20	6,998.00	9,453.20	57.46
+ GST 7.00/7.00% (S\$)	1,151.58	489.86	661.72	57.46
Nett Amount (S\$)	17,602.78	7,487.86	10,114.92	57.46

INSPECTION

Date of Assignment:	10/08/2021		
Date Inspected:	11/08/2021	Inspected At:	Team Auto Pro Pte Ltd - Sin Ming 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	7.0 days		

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6209U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,534.70 FL	*- FL
2	1		*BONNET LOCK ASSY	Not Damaged	234.60 FL	*- FL
3	1		*FRONT BUMPER	Cracked	1,450.00 FL	*1,050.90 FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	178.80 FL	*116.80 FL
5	1		*FRONT BUMPER LOWER GRILLE	Broken	326.00 FL	*146.50 FL
6	2		*FRONT BUMPER LOWER GRILLE SIDE GARNISH	No such part	262.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	486.00 FL	*295.80 FL
8	2		*HEADLAMP ASSY	Broken	3,909.60 FL	*3,088.00 FL
9	2		*HEADLAMP BRACKET	Broken	352.00 FL	*304.00 FL
10	1		*FRONT GRILLE	Broken	830.00 FL	*740.30 FL
11	1		*FRONT GRILLE LOGO	Necessary	78.00 FL	*56.00 FL
12	1		*FRONT GRILLE INNER PANEL	No such part	299.80 FL	*- FL
13	1		*FRONT GRILLE CHROME	Broken	168.00 FL	*168.00 FL
14	1		*FRONT GRILLE CHROME LOWER	No such part	175.00 FL	*- FL
15	1		*FRONT GRILLE UPPER BRACKET (CENTRE)	No such part	91.00 FL	*- FL
16	1		*FRONT FENDER LH	Bent	895.30 FL	*440.60 FL
17	1		*FRONT FENDER INNER COWLING LH	No such part	164.80 FL	*- FL
18	1		*FRONT FENDER EMBLEM HYBRID	Necessary	85.00 FL	*65.60 FL
19	1		*FRONT SUPPORT TOP PANEL	Not Damaged	898.00 FL	*- FL
20	1		*FRONT SUPPORT TOP PANEL GARNISH	Not Damaged	185.00 FL	*- FL
21	1		*RADIATOR	Not Damaged	987.90 FL	*- FL
22	1		*AIRCON CONDENSER	Not Damaged	985.00 FL	*- FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*FRONT SUPPORT TOP PANEL SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*FRONT SUPPORT TOP PANEL GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
33	1		*AIRCON FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,366.50	6,552.50
- List Item Discount on L Items 20.00/20.00% (S\$)	2,915.30	1,294.50
Total Parts (S\$)	12,451.20	5,258.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R RADIATOR	New	150.00	0.00
2	R&R AIRCON CONDENSER	New	150.00	0.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	20.00
6	PANEL BEATING	New	1,400.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,400.00	800.00
			Gross Labour Cost (S\$)	4,000.00
				1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >