



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 4083D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	N/S HEADLAMP	BROKEN	501.42	458.00
3	N/S HEADLAMP CLIPS @\$5.50	SERVICEABLE	16.50	-
1	N/S HEADLAMP TOP REFLECTOR O/S	BROKEN	230.34	230.34
1	FRONT N/S SIDE LAMP	BROKEN	245.00	245.00
2	FRONT N/S SIDE LAMP CLIPS @\$4.00	SERVICEABLE	8.00	-
1	FRONT BUMPER	BADLY DENTED	1,010.34	933.00
1	FRONT BUMPER SIDE RUBBER N/S	DENTED / BENT	353.71	353.71
1	FRONT BUMPER BRACKET N/S	SERVICEABLE	203.13	-
1	FRONT N/S CORNER PANEL	BADLY DENTED	524.54	346.00
1	FRONT N/S DOOR	BADLY DENTED / DEFORMED	1,534.85	1,455.00
1	FRONT N/S DOOR PILLAR	TO REPAIR SEE LABOUR	1,533.24	-
1	FRONT N/S DOOR CHECK	SERVICEABLE	86.45	-
1	FRONT N/S DOOR LOWER HINGES	BENT	168.26	168.26
1	FRONT N/S DOOR UPPER HINGES	BENT	168.26	168.26
1	FRONT N/S DOOR AIR VENT	WARPED	202.45	202.45
1	FRONT N/S STEP PANEL GARNISH	TO REPAIR SEE LABOUR	622.40	-
	LESS 25% DISCOUNT		-	-1,140.01
			7,408.89	3,420.01
<b><u>LABOUR</u></b>				
	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN FRONT N/S DOOR PILLAR, FRONT N/S STEP PANEL AND WHEEL ARCH AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR PILLAR AND FRONT N/S STEP PANEL GARNISH.		1,400.00	500.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		1,800.00	700.00
	CHECK ELECTRICAL.		100.00	30.00
	REMOVE AND REFIT FRONT N/S DOOR PARTS.		150.00	50.00
	TUFF KOTE.		50.00	30.00
	REWIRE FRONT PORTION AND N/S HEADLAMP BEAM.	NOT NECESSARY	50.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REWRITE DOOR LETTERING.		30.00	30.00
			3,580.00	1,340.00
GRAND TOTAL			10,988.89	4,760.01
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS3/GRB21007764/Etf3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.