

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21008387/VTF3E2**Date:** 12/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263887
Claimant Vehicle No :	SLW4123P	Insured Vehicle No :	SMR7595E
Date of Loss:	08/08/2021	Nature of Claim:	TP
		Claim No:	4448319496SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4123P	Engine No:	L15B4408139
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11208144
Reg. Date:	09/02/2018 (Man. Year: 2016)	Odometer:	21677 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/08/2021	
Date Inspected:	11/08/2021	Inspected At: Sin Hock Lee Motor Repair (HQ) 51 Ubi Ave 1, #01-09 Paya Ubi Industrial Park Singapore 408933
Estimated Period of Repair:	4.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
4	1		*REVERSE SENSOR	Cut	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*- F
7	1		*TAILGATE	Dented	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
12	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
13	1		*TAILGATE INNER BOARD	Cut	0.00 F	*- F
14	1		*SPARE TYRE BOARD	Cut	0.00 F	*- F
15	1		*REAR LH FENDER	Cut	0.00 F	*- F
16	1		*REAR RH FENDER	Cut	0.00 F	*- F
17	1		*TAILGATE SENSOR	Cut	0.00 F	*- F
18	1		*FRT BUMPER	Cut	0.00 F	*- F
19	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
20	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
21	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >