

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21008388/KUF3N2**Date:** 20/08/2021**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MPC20A00037804
Claimant Vehicle No :	SMU3815G	Insured Vehicle No :	SGL59K
Date of Loss:	09/08/2021	Nature of Claim:	TP
		Claim No:	DMPC2100257H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU3815G	Engine No:	PE21332108
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE I4 (A)	Chassis No:	JM6GL1073L0402768
Reg. Date:	11/08/2020 (Man. Year: 2019)	Odometer:	9536 km
Colour:	Metallic Pearl Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	819.20	819.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	1,710.00	260.00	13.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,789.20	2,529.20	260.00	9.32
+ GST 7.00/7.00% (S\$)	195.24	177.04	18.20	9.32
Nett Amount (S\$)	2,984.44	2,706.24	278.20	9.32

INSPECTION

Date of Assignment:	11/08/2021	
Date Inspected:	12/08/2021	Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Aug 2021)

Parts: 143 MAZDA 6 2.0 SEDAN EXECUTIVE I4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU3815G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	982.00 FL	*982.00 FL
2	1		*SET FRONT DOOR FRAME TAPES RH	Necessary	42.00 FL	*42.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	1,024.00
					- List Item Discount on L Items 20.00/20.00% (\$)	204.80
					Total Parts (\$)	819.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK/CLEAR FAULT CODES AFTER REPAIR	New	80.00	60.00
2	TUFF COAT	New	40.00	30.00
3	TO KNOCK DENTS ON ROCKER PANEL RH + RENEW OF PARTS	New	350.00	320.00
4	TO SPRAY PAINT (INCLUDING REAR DOOR RH + REAR FENDER RH + BLEND FRONT FENDER RH + ROOF SIDE PANEL RH/PEARL RED)	New	1,500.00	1,300.00
Gross Labour Cost (\$\$)			1,970.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >