

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008389/UEA3Q2
Date: 29/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900105228
Claimant Vehicle No :	FBR4848B	Insured Vehicle No :	GBJ5875H
Date of Loss:	22/07/2021	Nature of Claim:	TP
		Claim No:	9115074590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR4848B		
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Engine No:	H336E0078949
Reg. Date:	13/07/2020 (Man. Year: 2020)	Chassis No:	MH3SH0846LK010499
Colour:	Blue	Odometer:	20825 km
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70-15	Rear Tyre Size:	140/70-14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	228.00	68.40	159.60	70.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	80.00	235.00	74.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	543.00	148.40	394.60	72.67
+ GST 7.00/7.00% (S\$)	38.01	10.39	27.62	72.67

Nett Amount (\$\$)	581.01	158.79	422.22	72.67
<hr/>				
+ Loss of Use (1.0 x S\$20.00/day) (\$\$)		20.00		
+ Doc/Search Fee (\$\$)		2.00		
<hr/>				
Nett Liability (\$\$)		180.79		
<hr/>				

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY FRONT UNDER 2	Scratched	48.00 F	*48.00 FL
2	1		*COVER TAIL RH (MATTE BLUE) (Scratched)	Not Consistent With The Impact	55.00 F	*- FL
3	1		*COWLING FRONT RH (MATTE BLUE)	Scratched	28.00 F	*28.00 FL
4	1		*EMBLEM 3D XMAX LOGO	Not Necessary	35.00 F	*- FL
5	1		*PROTECTOR EXHAUST (Scratched)	Not Consistent With The Impact	62.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	228.00 76.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 7.60
					Total Parts (\$)	228.00 68.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	315.00	80.00
Gross Labour Cost (S\$)			315.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >