



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 2135G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	TO REPAIR SEE LABOUR	855.00	-
1	FRONT BUMPER	DISTORTED	801.00	789.00
1	FRONT BUMPER LOWER SKIRTING	TORN	950.00	750.00
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	182.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	344.00	341.00
1	FRONT BUMPER SIDE RETAINER O/S	BENT	121.00	115.00
1	FRONT BUMPER FOG LAMP COVER O/S	TORN	98.00	98.00
1	SET FRONT BUMPER LOWER CARBON	NOT NECESSARY	680.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT GRILLE	NOT NECESSARY	197.00	-
1	FRONT GRILLE LOGO	NOT NECESSARY	38.00	-
1	HEADLAMP O/S	CRACKED	901.00	624.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	745.00	-
1	AIR CON CONDENSER	NOT NECESSARY	866.00	-
1	RADIATOR	NOT NECESSARY	1,021.00	-
1	WIPER WASHER TANK	TORN	242.00	185.00
1	FRONT FENDER O/S	BUCKLED	689.00	677.00
1	FRONT FENDER INNER SHIELD O/S	TORN	282.00	266.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	45.00
1	FRONT FENDER OUTER CHROME MOULDING O/S	NOT FITTED	48.00	-
1	FRONT SHOCK ABSORBER SPORT O/S	SERVICEABLE	900.00	-
1	FRONT LOWER ARM O/S	BENT	455.00	299.00
1	FRONT KNUCKLE ARM O/S	BENT	561.00	398.00
1	FRONT KNUCKLE ARM BEARING O/S	DAMAGED	250.00	215.00
1	FRONT DRIVE SHAFT O/S	NOT NECESSARY	1,250.00	-
1	FRONT STEERING RACK ASSY	NOT NECESSARY	1,866.00	-
1	FRONT TYRE O/S	SERVICEABLE	200.00	-
	LESS 10% DISCOUNT		-	-485.20
			14,642.00	4,366.80

Report Ref No. CS/SMO21008390/Uuf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT SPORT RIM O/S (SN)	CUT / BENT	900.00	450.00
			900.00	450.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		100.00	50.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		380.00	120.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,080.00
			3,500.00	1,950.00
<b>GRAND TOTAL</b>			<b>19,042.00</b>	<b>6,766.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,400.00</b>

Report Ref No. CS/SMO21008390/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.