



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008390/Uuf3n2	
			Date: 23/08/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLZ 3198P	Veh. Inspected	SJY 2135G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102350/RUC	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	11/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	mitsubishi LANCER GLX (A)	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JMYSRCS3AAU000245	Colour	BLACK	
Odometer	145590 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	HABILEAD	6 mm	
L/H Front Tyre	205/50 R16	HABILEAD	6 mm	
R/H Rear Tyre	205/50 R16	HABILEAD	6 mm	
L/H Rear Tyre	205/50 R16	HABILEAD	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/08/2021	Inspection Date	11/08/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	