

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21008397/R1vce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 20/08/2021 SINGAPORE 068811 ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 1231T CB 6520E** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03F19 Excess (\$) 0.00 **CHAN KIAN CHUAN Assign Date** 11/08/2021 Assign From **Vehicle Particulars & Condition** 2. KING LONG XMQ6900K Make & Model 6693 c.c HIDDEN 2010 Engine No. Year of Reg. LA6R1DSB9AB201286 WHITE Chassis No. Colour 749389 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 275/70 R22.5 **FALKEN** 8 mm 275/70 R22.5 **FALKEN** L/H Front Tyre 8 mm 275/70 R22.5 (D) **FALKEN** R/H Rear Tyre 8/8 mm 275/70 R22.5 (D) FALKEN L/H Rear Tyre 8/8 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 30/07/2021 16/08/2021 (02:02 PM) Inspect Date / Time Accident Date 2A Second Chin Bee Road Singapore 618781 Survey held at Repairer WESTPOINT TRANSIT PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM21008397/R1vce2

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days