

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21008398/Dga3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	26/07/2022	
	ATTN:KHOR SAW	THENG	1	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMF 8934S	Veh. Inspected		SHC 8703S	
	Policy No.	GA421169	Coverage (\$)		0.00	
	Claim No.	S1M03F9P	Excess (\$)		0.00	
	Assign From		Assign Date		11/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	KMHLB41UMGU080583	Colour		BLUE	
	Odometer	677555 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/08/2021	Inspection Date	•	11/08/2021	
	Survey held at	BIFROST AUTO PTE LTD	•			
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	-					