



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2106157

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 02/09/2021
Reference CC4/FCI21008401/Ura3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBK 1698Z
Insured Veh. GBJ 3042H
Claim No. D21002280MFCV
Policy No. D-21097524MFCV
Accident Date 06/08/2021
Inspection Date 11/08/2021

Description	Total
Survey Inspection	276.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	276.00
GST (7%)	19.32
Grand Total	295.32

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008401/Ura3q2	
			Date: 02/09/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 3042H	Veh. Inspected	FBK 1698Z	
Policy No.	D-21097524MFCV	Coverage (\$)	0.00	
Claim No.	D21002280MFCV	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	11/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YBR125	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	LBPKE1789E0028774	Colour	RED	
Odometer	40452 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	TIMSUN	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.00-18	TIMSUN	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2021	Inspection Date	11/08/2021	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 1698Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AXLE WHEEL FRONT (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	23.00	-
1	BRACKET FOOTREST LH	BENT	38.00	38.00
1	BRACKET FOOTREST RH	BENT	38.00	38.00
1	BRACKET UNDER FORK	NOT NECESSARY	180.00	-
1	COVER TAIL LH (RED)	TO REPAIR SEE LABOUR	90.00	-
1	CROWN HANDLE	NOT NECESSARY	75.00	-
1	FOOTREST FRONT	TORN	55.00	55.00
1	FOOTREST REAR ASSY LH	DAMAGED	15.00	15.00
1	FOOTREST REAR ASSY RH	CUT	15.00	15.00
1	FORK FRONT ASSY LH	NOT NECESSARY	252.00	-
1	FORK FRONT ASSY RH	NOT NECESSARY	252.00	-
1	GASKET EXHAUST PIPE	NECESSARY	5.00	5.00
1	LAMP SIGNAL REAR LH	NOT NECESSARY	28.00	-
1	MUDGUARD FRONT (RED)	NOT NECESSARY	98.00	-
1	PEDAL BRAKE	TO REPAIR SEE LABOUR	88.00	-
1	PEDAL GEAR (SHORT)	NOT NECESSARY	19.00	-
1	PIPE EXHAUST ASSY	DENTED/ BENT	399.00	399.00
2	RUBBER FOOTREST FRONT @\$14.00	TORN	28.00	28.00
1	STAND SIDE	NOT NECESSARY	38.00	-
1	SET STEERING CONE	NOT NECESSARY	66.00	-
1	STOPPER 3	NOT NECESSARY	16.00	-
	LESS 10% DISCOUNT		-	-59.30
			1,818.00	533.70
	<u>LABOUR</u>			
	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS.INCLUSIVE OF THE REPAIR OF COVER TAIL LH (RED) AND PEDAL BRAKE .		504.00	280.00
	REPAIR REAR BODY ALIGNMENT.		280.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSPORT CHARGES.		45.00	35.00
			829.00	515.00
GRAND TOTAL			2,647.00	1,048.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC4/FCI21008401/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBK 1698Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBK 1698Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

