

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21008407/UES3Q2
Date: 13/09/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd
Claimant Vehicle No : SJH4965D
 Date of Loss: 06/08/2021

Policy No:
Insured Vehicle No : SLL8016Y
 Nature of Claim: TP
 Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH4965D**
 Make & Model: TOYOTA CAMRY, 2.0 (A)
 Reg. Date: 12/08/2008 (Man. Year: 2008)
 Colour: Beige
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1AZE108406
 Chassis No: MR053BK4107032109
 Odometer: 282488 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No
 Footbrake (Serviceable): Yes
 Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16
 Front Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm

Rear Tyre Size: 215/60 R16
 Rear Left Side: Yokohama 6 mm
 Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,705.50	821.82	1,883.68	69.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	900.00	780.00	46.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,385.50	1,721.82	2,663.68	60.74
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	4,385.50	1,300.00	3,085.50	70.36
+ GST 7.00/7.00% (S\$)	306.99	91.00	215.99	70.36
Nett Amount (S\$)	4,692.49	1,391.00	3,301.49	70.36
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 16/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Falcon-Air Auto Services Pte Ltd (Tampines)
 Blk 9006 #01-200 Tampines St 93
 Singapore

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH4965D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	645.00 FL	*566.10 FL
2	1		*REAR BUMPER SIDE RETAINER -LONG	N/S Necessary	156.00 FL	*78.00 FL
3	2		*REAR BUMPER SIDE RETAINER -SHORT	Not Necessary	120.00 FL	*- FL
4	1		*N/S REAR FENDER INNER SHIELD	Torn	185.00 FL	*185.00 FL
5	1		*N/S REAR WHEEL BEARING	Not Necessary	223.00 FL	*- FL
6	1		*N/S REAR SHOCK ABSORBER	Not Necessary	356.00 FL	*- FL
7	1		*N/S REAR KNUCKLE ARM	Not Necessary	379.00 FL	*- FL
8	1		*N/S REAR UPPER ARM	Not Necessary	285.00 FL	*- FL
9	1		*N/S REAR LOWER ARM	Not Necessary	325.00 FL	*- FL
10	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
11	1		*SET N/S REAR FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*N/S REAR RIM (LOCAL REPAIR)	Cut	600.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,374.00	1,029.10
- List Item Discount on L Items 25.00/25.00% (\$)	668.50	207.28
Total Parts (\$)	2,705.50	821.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	20.00
2	TO REMOVE /REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS	New	150.00	80.00
3	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
4	TRANSFER TYRE AND BALANCING	New	50.00	0.00
5	TRANSFER REVERSE SENSOR TO NEW BUMPER	New	60.00	40.00
6	REPLACE REAR UNDERCARRIAGE	New	250.00	0.00
7	LABOUR /PANEL BEATING	New	500.00	300.00
8	SPRAY PAINTING	New	500.00	400.00
Gross Labour Cost (S\$)			1,680.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >