111 AUTO PTE LTD

INVOICE

To:

1

Vivien Ng Jeok Yong

Bik 408 Jurong West Street 42 #10-679 Singapore 640408 Tax Invoice:

23032021/2227

Date:

7/5/2021

Vehicle No.: Make / Model: SBB2227R

Chassis No,:

Toyota Vios MR053HY9305033992

Accident Date:

23/3/2021

S/N	DESCRIPTION
0/14	DECOMMINE

Costs of Repair

Amount S\$

\$

9,700.00

\$ 9,700.00 7% GST \$ 679.00 Amount Due S\$ \$ 10,379.00

Please acknowledge recepit of vehicle

Customer's Signature

Received in good order & condition Goods sold are not refundable For & on behalf

111 AUTO PTE LTD

Prepard by Ms Wang

111 AUTO PTE LTD

81 Ubi Avenue 4

#09-18 UB. One Singapore 408830

T: 8811 0111

Company Registration Number: 201730375K



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

21-7556

Date:

8/4/2021

INVOICE NO.

7556

Vivien Ng Jeok Yong c/o 111 Auto Pte Ltd 81 Ubi Avenue 4 #09-18 Ub.One Singapore 408830

Registration No.

SBB2227R

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

:	S/No.	Description of Services Provided	Qty	Amount
•	1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$914.00
			Total amount	\$914.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

 \sim

L. L. Tan (Ms)

Principal Consultant

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- ◆ IA Accounting & Consultancy Pte Ltd
 ◆ Infoknights International Services (Philippines)
 ◆ IABN Pte Ltd www.iaconsultingsg.com



Our reference:

21-7556

Date:

8/4/2021

c/o 111 Auto Pte Ltd 81 Ubi Avenue 4 #09-18 Ub.One Singapore 408830

Dear Sirs

RE:

Road Traffic Accident on 23/3/2021

Vivien Ng Jeok Yong

In accordance with your instructions received in this office or

25/3/2021

, we made arrangements to

examine the vehicle on

25/3/2021

at above-mentioned address. The following data was

recorded:

Vehicle details


Make	Toyota	Registration	SBB2227R
Model	Vios	Chassis	MR053HY9305033992
Colour	Gold	Gearbox	Auto
Odometer	164601km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	185/60R15	85% Yokohama
Front right	185/60R15	85% Yokohama
Rear left	185/60R15	85% Yokohama
Rear right	185/60R15	85% Yokohama

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$9,700.00 and 8 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171



Our reference

21-7556

Date

8/4/2021

Page

2

Section A: Damaged Parts Assessment

Part's Description		Condition As inspected	Repairer's Estimate	Our Adjustment
<u>List Items:</u>				
Bonnet	1	repair.respray	552,50	0.00
Bonnet hinge @\$43.20	2	bent	86.40	86.40
Bonnet lock	1	jammed	78.80	78.80
Front bumper	1	broken	457.80	457.80
Front bumper side retainer @\$56.20	2	necessary	112.40	112.40
Front bumper tow cover	1	mising	28.20	28.20
Front bumper lower grille	1	reuse	88.50	0.00
Front bumper fog lamp ring @\$49.20	2	rh damaged lh reuse	98.40	49.20
Front bumper fog lamp @\$425.80	2	rh damaged lh reuse	851.60	425.80
Front bumper top inner garnish	1	damaged	95.60	95.60
Front bumper reinforcement	1	bent	326.41	326.41
Front bumper impact bracket @\$207.70	2	bent	415.40	415.40
Front bumper side bracket @\$85.60	2	bent	171.20	171.20
Front radiator grille assy	1	broken	233.50	233.50
Front bumper logo	1	necessary	48.50	48.50
Front head lamp @\$444.25	2	damaged	888.50	888.50
Front fender @\$498.50	2	bent/warped	997.00	997.00
Front fender cowling @\$139.05	2	refix	278.10	0.00
Front fender emblem 'VVTi' rh	1	necessary	36.50	36.50
Front support panel	1	bent	771.60	771.60
Front support panel side garnish @\$133.80	4	damaged	535.20	535.20
Front air con condenser	1	refix	937.80	0.00
Front head lamp top panel @\$85.60	2	bent	171.20	171.20
Front radiator	1	refix	1522.71	0.00
Front door lh	1	repair.respray	986.40	0.00
Wiper tank	1	dented	122.00	122.00

Subsidiaries of Impact Analysis Consultant:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

[■] Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ 1A Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ 1A Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ 1A Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ 1A Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ 1A Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Lt

 [◆] IA Accounting & Consultancy Pte Ltd
 ◆ Infoknights International Services (Philippines)
 ◆ IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7556

Date 8/4/2021				
Wiper tank motor	1	ceased	95.40	95.40
Wiper panel	1	deformed	186.79	186.79
Wiper panel bracket	1	damaged	45.80	45.80
Front drive shaft rh	1	damaged	1025.45	1025.45
Front lower arm rh	1	damaged	233.00	233.00
Front shock absorber rh	1	damaged	254.80	254.80
Front knuckle bearing / hub rh	1	necessary	275.12	275.12
Front linkage @\$156.10	2	damaged	312.20	312.20
Front tie rod @\$127.60	2	damaged	255.20	255.20
Front engine under cover	1	damaged	164.80	164.80
Steering rack and pinion	1	damaged	1373.10	1373.10
	Sub- Total	cost	15113.88	10272.87
	Percentage discount :	25%	3778.47	2568.22
	Sub-Total costs	for parts	11335.41	7704.65
Special Nett Items:				
Front bumper Iclips	set	necessary	50.00	50.00
	Sub-Total costs	for parts	50.00	50.00
Parts Repair				
*	*	*	0.00	0.00
	Sub- Total o	costs	0.00	0.00
	Total costs fo	11385.41	7754.65	

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Subsidiaries of Impact Analysis Consultant:

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7556

Date

8/4/2021

Page

3

Section B: Labour Cost Calculation

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

	Hourly rat	e Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	27	\$ 1,215.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-co	ntract work.	\$ 1,400.00
Apply rust proofing on the adjacent panels.	Sub-co	ntract work.	\$ 60.00
Wiring and bulb checking	\$ 45.00	1	\$ 45.00
Remove / refix aircon condenser and refill aircon gas	\$ 45.00	2.5	\$ 112.50
Remove and refix front undercarriage works	\$ 45.00	10	\$ 450.00
Specialist charges - Conduct front chassis alignment	-	-	\$ 250.00
Specialist charges - Wheel alignment	-	-	\$ 60.00
	Total	abour cost	\$ 3,592.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

[•] IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7556

Date

8/4/2021

Section C: Summary Table of Total Repair Cost

Des	cription	Cost	
Damaged Parts Assessment (See section A)		\$7,754.65	
Further discount	20%	\$1,550.93	
Recommended cost of parts		\$6,203.72	(1)
	st Calculation ection B)	\$3,592.50	(2)
	epair Cost f to hundred)	\$9,700.00	(1) + (2)

We would recommend a sum of \$9,700.00 and working days for repair. No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Ingineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diplomd.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171