

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008415/APA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900019440
Claimant Vehicle No :	SMH1095Z	Insured Vehicle No :	SKU6392M
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	2324024302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1095Z	Engine No:	CVK070646
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Chassis No:	WAUZZZF4XKN000490
Reg. Date:	11/01/2019 (Man. Year: 2018)	Odometer:	30739 km
Colour:	Brown		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,362.00	11,584.80	14,777.20	56.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,790.00	1,590.00	47.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,742.00	13,374.80	16,367.20	55.03
Approved Total (Overridden) (S\$)		10,700.00		
(S\$)	29,742.00	10,700.00	19,042.00	64.02
+ GST 7.00/7.00% (S\$)	2,081.94	749.00	1,332.94	64.02
Nett Amount (S\$)	31,823.94	11,449.00	20,374.94	64.02
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,256.45		
Global Sum Settlement (S\$)		12,200.00		

INSPECTION

Date of Assignment:	11/08/2021	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	11/08/2021 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	7.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE INNER BRACKET	Cracked	525.00 F	*168.00 FL
2	1		*FRONT GRILLE ASSY	Cracked	985.00 F	*985.00 FL
3	1		*FRONT GRILLE SENSOR	Not Necessary	380.00 F	*- FL
4	2		*HEAD LAMP TOP BRACKET	Not Necessary	302.00 F	*- FL
5	1		*FRONT HEAD LAMP	N/S Cracked	10,592.00 F	*5,296.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	855.00 F	*855.00 FL
7	1		*FRONT BUMPER	Deformed	1,820.00 F	*1,820.00 FL
8	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	210.00 F	*- FL
9	1		*FRONT BUMPER NUMBER PLATE	Cracked	50.00 F	*50.00 FL
10	1		*FRONT BUMPER SPONGE	Cut	324.00 F	*105.00 FL
11	8		*FRONT BUMPER CLIPS	Necessary	52.00 F	*30.00 FL
12	2		*FRONT BUMPER FOG LAMP CHROME	Not Necessary	196.00 F	*- FL
13	1		*FRONT BUMPER TOWING COVER	Not Necessary	80.00 F	*- FL
14	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	1,050.00 F	*- FL
15	1		*BRACE PANEL	Not Necessary	215.00 F	*- FL
16	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	830.00 F	*- FL
17	1		*REAR BOOT LID EMBLE LOGO	Not Necessary	82.00 F	*- FL
18	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
19	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	90.00 F	*- FL
20	2		*REAR BOOT LID TAIL LAMP	Not Necessary	1,492.00 F	*- FL
21	1		*REAR BOOT LID A4 LOGO	Not Necessary	59.00 F	*- FL
22	1		*REAR BUMPER	Deformed	1,850.00 F	*1,850.00 FL
23	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	940.00 F	*470.00 FL
24	2		*REAR BUMPER SIDE BRACKET	Not Necessary	250.00 F	*- FL
25	1		*REAR BUMPER REINFORCEMENT	Dented	710.00 F	*710.00 FL
26	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	330.00 F	*- FL
27	10		*REAR BUMPER CLIPS	Necessary	60.00 F	*30.00 FL
28	1		*REAR BUMPER LOWER LIP	Deformed	452.00 F	*358.00 FL
29	1		*REAR BUMPER LOWER GRILLE	Deformed	325.00 F	*145.00 FL
30	2		*REAR BUMPER LOWER SIDE GARNISH	Not Necessary	156.00 F	*- FL
31	1		*REAR END PANEL	Repair	1,050.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	26,362.00	12,872.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,287.20
Total Parts (\$)	26,362.00	11,584.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO CHECK WHEEL ALIGNMENT COMPUTER	New	120.00	0.00
3	TUFF KOTE	New	120.00	60.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	60.00
5	TO REMOVE & REFIX FRONT GRILLE SENSOR	New	100.00	60.00
6	PANEL BEATING	New	1,400.00	800.00
7	SPRAY PAINTING	New	1,400.00	750.00
Gross Labour Cost (\$\$)			3,380.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >