Correspondence Address. 1 Simei St 3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email. pasvcs@hotmail.com

Business Reg 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0510819

Date of Report

: 13/09/2019

To: Mr Leo Se Hiong

C/o. 53 Ubi Avenue 1 #01-33

Paya Ubi Industrial Park Singapore 408934

Report requested by : Mr Leo Se Hiong

Date of Assignment : 29/08/2019

Date of Accident

: 22/08/2019

Date of Inspection

Claim No.

: 29/08/2019

: Third Party Claim

Policy No.

.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SKX1688C

Engine Capacity (cc) : 1496cc

Make & Model

: Honda Vezel

Mileage (km)

: 68087km

Date of Registration

Colour

: 28/09/2016 : Morpho Blue Pearl

Chassis / Frame No. : RU31128200 Engine No.

: LEB5078218

TYRE CONDITION

Front LH

: 6 mm

Front RH

: 6 mm

Make

: Dunlop

Make

: Dunlop

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

: Dunlop

Make

: Dunlop

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

Steering

: Serviceable : Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location :

M/s. My Car Consultant Pte Ltd

53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate

: S 7,403.76

Revised Amount

: 5 6,378.16

Less Excess

; S

Recommended Reserve

: \$ 5,100.00 (Lump Sum)

Estimated Normal Period of Repairs

: 5 Working Days

Disclaimer: This report is intended for the exclusive use of the addresses solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Qualified Loss Adjusters And Motor Appraisers Correspondence Address 1 Simei St 3 #02-24 S(529890) Mobile 9295 2204 Fax 6722 8508 Email pasves@hotmail.com

Business Reg. 201404434D

Vehicle No: SKX1688C

Report No.: PAS/TP/0510819

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. My Car Consultant Pte Ltd, 53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The front bumper, front support panel, front fenders, headlamps, etc.

Other parts were also found damaged, (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$6,378.16.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,100.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address 1 Simei St 3 #02-24 S(529890) Mobile 9295 2204 Fax 6722 8508 Email passvcs@hotmail.com Business Reg. 201404434D

Business Reg. 201404434D

Vehicle No. : SKX1688C

Report No.: PAS/TP/0510819

APPRAISEMENT SCHEDULE

| S/No. | Qty | Parts Descriptions | Condition | | | 2-53 | pairer's imate (S\$) | Our Assessment (S\$) | | | |
|-------|-------|------------------------------------|-------------------|----------------------|---------------|------|-----------------------------|-------------------------|------|-------------|--|
| | | | RH-M | 4 | / | Lat | imate (55) | 71.33 | caan | uent (53) | |
| 1 | 2 pcs | Headlamp (LED) R/L | | 5 | 1,775.00 | \$ | 3.550.00 | | S | 3.550.00 | |
| 2 | 8 pes | Frt bumper clip | Necessary | 5 | 3.60 | \$ | 28.80 | | S | 28.80 | |
| 3 | 2 pes | Fri bumper support R/L RY-MU | Broken Cracked | S | 39,30 | \$ | 78.60 | | S | 78.60 | |
| 4 | 2 pes | Frt bumper retainer R/L | Cracked/Necessary | S | 58.00 | \$ | 116.00 | | S | 116.00 | |
| 5 | 1 pc | Frt bumper reinforcement | Dented | | | S | 548.20 | | S | 548.20 | |
| 6 | 1 pc | Frt support panel assy | Dented/Repair | | | \$ | 682.00 | | S | . \ | |
| 7 | 1 pc | Frt support panel top garnish | Dented/Cracked | | | 5 | 172.30 | | S | 172.30×NN | |
| 8 | 9 pcs | Frt support panel top garnish elip | Necessary | S | 3.20 | \$ | 28.80 | | S | 28.80 | |
| 9 | 1 pc | Frt support panel | Dented/Repair | | | | (Refer labour no. 2, 3 & 4) | | | | |
| 10 | 1 pc | Frt fender R/L | Dented/Repair | | | | (Refer labour no. 3 & 4) | | | | |
| | | | | | | S | 5,204.70 | | \$ | 4.522.70 | |
| | | | | Less | Discount: 20% | \$ | 1,040.94 | 20% | \$ | 904.54 | |
| | | | List | ist Parts Sub-Total: | | \$ | 4,163.76 | | S | 3,618.16 | |
| 1 | 1 pc | Frt bumper (Mugen, w Grille) | Dented/Cracked | | S/N | \$ | 1,200.00 | | s | L200.00 700 | |
| | | | Specia | l Nett S | ub-Total : | \$ | 1,200.00 | | S | 1,200.00 | |
| | | | | | | | | | | | |
| | | | | Par | rts Total : | S | 5,363.76 | | \$ | 4,818.16 | |



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address 1 Simel St 3 #02-24 S(529890) Mobile 9295 2204 Fax 6722 8508 Email pasves@hotmail.com Business Reg. 201404434D

| Vehi | Vehicle No.: SKX1688C Report No.: PAS/TP/051081 | | | | | |
|------|---|----|--------------------------|---------|----------|-----|
| S/No | . Labour Descriptions | | pairer's timate (S\$) | Assessi | | |
| 1 | To check electrical system and calibrate/focus headlamp. | s | 60.00 | S | 50.00 | 30 |
| 2 | To remove, reinstall radiator, a/c condenser and pipings for necessary repairs. (Include pressure test cooling system and vacuum, recharge a/c gas) | s | 180.00 | s | 160.00 | × |
| 3 | To straighten, repair, realign on affected area and replace damaged parts. | \$ | 800.00 | S | 550.00 | 400 |
| 4 | To spray painting, blending on affected and adjacent area. | \$ | 1,000.00 | S | 800.00 | 200 |
| | Labour Total : | S | 2,040.00 | S | 1,560.00 | |
| | Total (Parts & Labour): | S | 7,403.76 | | 6,378.16 | - |

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is 5 5,100.00

Under normal circumstances, the repairs should be completed within a reasonable period

- 5 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)
- 52 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

4 days