



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107227

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 19/10/2021
Reference CC4/FCI21008421/Kpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMF 3055L

Insured Veh. SBS 6515T

Claim No. D21002282MFBP

Policy No. D-20096309MFBP

Accident Date 07/08/2021

Inspection Date 16/08/2021

Description	Total
Survey Inspection	287.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	287.00
GST (7%)	20.09
Grand Total	307.09

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008421/Kpa3q2	
			Date: 19/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 6515T	Veh. Inspected	SMF 3055L
	Policy No.	D-20096309MFBP	Coverage (\$)	0.00
	Claim No.	D21002282MFBP	Excess (\$)	0.00
	Assign From	ESTHER LIM	Assign Date	11/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MRHFC5650JT001787	Colour	METALLIC PEARL WHITE
	Odometer	53297 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R16	YOKOHAMA	9 mm
	L/H Front Tyre	215/55 R16	YOKOHAMA	9 mm
	R/H Rear Tyre	215/55 R16	YOKOHAMA	9 mm
	L/H Rear Tyre	215/55 R16	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/08/2021	Inspection Date	16/08/2021
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 3055L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	617.50	617.50
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	198.00	-
1	REAR BUMPER LH SIDE RETAINER	DISTORTED	15.00	15.00
1	REAR BUMPER REVERSE SENSOR	SHORTED	148.50	148.50
1	REAR BUMPER LH REFLECTOR	DENTED / CUT	14.80	14.80
6	REAR BUMPER CLIP @\$3.80	NECESSARY	22.80	22.80
1	LH TAILLAMP	BROKEN	321.80	321.80
1	LH TAILLAMP LOWER PANEL	TO REPAIR SEE LABOUR	69.30	-
1	REAR BOOT EMBLEM 'CIVIC'	NOT NECESSARY	15.10	-
1	REAR BOOT EMBLEM 'I-VTEC'	NOT NECESSARY	15.20	-
1	REAR BOOT LOGO	NOT NECESSARY	14.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	287.50	-
1	TAILLAMP LOWER RETAINER	DENTED	12.00	12.00
1	REAR BOOT REFLECTOR	CRACKED	139.60	139.60
	LESS 20% DISCOUNT		-378.26	-258.40
			1,513.04	1,033.60
	<u>LABOUR</u>			
	REMOVE & REFIX & PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT ,LH TAILLAMP LOWER PANEL AND REAR END PANEL.		700.00	450.00
	SPRAY PAINTING ON ACCIDENT AFFECTED AREAS.		750.00	660.00
	RUSTPROOFING.	NOT NECESSARY	30.00	-
			1,480.00	1,110.00
	GRAND TOTAL		2,993.04	2,143.60



RECOMMENDED COST OF REPAIRS			2,143.60
-----------------------------	--	--	----------

Report Ref No. CC4/FCI21008421/Kpa3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 3055L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 3055L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 3055L

RE-INSPECTION



HONDA AUTOMOBILE(THAILAND)CO.,LTD.
CHASSIS NO. MRHFC5650JT001787
ENGINE NO. R16B2-5502055
TEC J SA5 NH-788P A