12/14/21, 11:14 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21008422/R1GA3Q2

Date: 14/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472286-05

Claimant Vehicle No: SLS459T Insured Vehicle No: SLD6122D

Date of Loss: 30/07/2021 Nature of Claim: TP Claim No: 6934580703SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS459T

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ513828

Reg. Date: 06/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V2J1007882

Colour: Silver Odometer: 74978 km

Engine Capacity: 999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,442.00	550.00	1,892.00	77.48
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,442.00	550.00	1,892.00	77.48
	+ GST 7.00/7.00% (S\$)	170.94	38.50	132.44	77.48
	Nett Amount (S\$)	2,612.94	588.50	2,024.44	77.48
	+ Loss of Use (2.0 x	S\$50.00/day) (S\$)	100.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	690.50		

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 16/08/2021 Inspected At: 281 ALEXANDRA ROAD

Repairer:Premium Automobiles Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REINSTALL LHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	0.00
2	TO REPAIR REAR RIGHT DOOR	New	1,000.00	0.00
3	TO RESPRAY REAR RIGHT DOOR	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
	Gross Labor	ur Cost (S\$)	2,442.00	550.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >