

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008423/T1UF3Q2
Date: 10/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100435936
Claimant Vehicle No :	SJV5015R	Insured Vehicle No :	GBE3143B
Date of Loss:	08/08/2021	Nature of Claim:	TP
		Claim No:	2821669344SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV5015R		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	G4FC9H336409
Reg. Date:	28/01/2010 (Man. Year: 2009)	Chassis No:	KNAFU411MA5170966
Colour:	White	Odometer:	124552 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/10/21, 4:45 PM

Adjuster Report

Date of Assignment: 12/08/2021

Date Inspected: 12/08/2021

Estimated Period of Repair: 16.0 days

Inspected At:

Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$24,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
9	1		*FRT LH BUMPER FOG LAMP	Cracked	0.00 F	*- F
10	1		*FRT GRILLE	Cracked	0.00 F	*- F
11	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
12	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
13	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*BONNET	Bent	0.00 F	*- F
17	1		*BONNET LOCK	Bent	0.00 F	*- F
18	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
19	2		*AIR CON SIDE GARNISH	Deformed	0.00 F	*- F
20	1		*RADIATOR	Bent	0.00 F	*- F
21	1		*RADIATOR FAN ASSY	*Check	0.00 F	*- F
22	1		*AIR DUCT	Deformed	0.00 F	*- F
23	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
24	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
25	1		*FRT LH FENDER	Repair	0.00 F	*- F
26	1		*FRT RH FENDER	Repair	0.00 F	*- F
27	1		*REAR NUMBER PLATE	Deformed	0.00 F	*- F
28	2		*REAR NUMBER PLATE LAMP	Distorted	0.00 F	*- F
29	1		*REAR BUMPER	Deformed	0.00 F	*- F
30	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
31	1		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
32	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
33	1		*REAR BUMPER SPONGE	Deformed	0.00 F	*- F
34	1		*REAR BUMPER LOWER SPOILER	Deformed	0.00 F	*- F
35	1		*REVERSE SENSOR	Not Working	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL	Bent	0.00 F	*- F
37	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
38	1		*REAR LH TAILLAMP	Necessary	0.00 F	*- F
39	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
40	1		*BOOTLID	Bent	0.00 F	*- F
41	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
42	1		*BOOTLID MOULDING	Deformed	0.00 F	*- F
43	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
44	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
45	1		*BOOTLID LOCK	Bent	0.00 F	*- F
46	1		*BOOTLID RUBBER	Necessary	0.00 F	*- F
47	2		*BOOTLID HINGE	Bent	0.00 F	*- F
48	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
49	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
50	1		*SPARE TYRE	*Check	0.00 F	*- F
51	1		*SPARE TYRE LOCK SCREW	Bent	0.00 F	*- F
52	1		*REAR EXHAUST PIPE	*Check	0.00 F	*- F
53	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
54	1		*REAR RH CHASSIS MEMBER	Repair	0.00 F	*- F
55	1		*REAR LH FENDER	Bent	0.00 F	*- F
56	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*- F
57	1		*REAR LH FENDER INNER SHIELD	Deformed	0.00 F	*- F
58	1		*REAR RH FENDER	Repair	0.00 F	*- F
59	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*- F
60	1		*REAR RH FENDER INNER SHIELD	*Check	0.00 F	*- F
61	1		*REAR FENDER EXTENSION PANEL LH	Repair	0.00 F	*- F
62	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
63	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
64	1		*REAR LH DOOR	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)**0.00****0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >