

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008425/BEA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100052614-13
Claimant Vehicle No :	SMN3588Z	Insured Vehicle No :	SJA3022T
Date of Loss:	09/08/2021	Nature of Claim:	TP
		Claim No:	9643341724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3588Z	Engine No:	S530436420
Make & Model:	MAZDA AXELA, 1.5 (A)	Chassis No:	BMLFP101462
Reg. Date:	02/08/2019 (Man. Year: 2019)	Odometer:	121987 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,325.04	5,004.80	1,320.24	20.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,440.00	1,100.00	43.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,865.04	6,444.80	2,420.24	27.30
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	8,865.04	5,150.00	3,715.04	41.91
+ GST 7.00/7.00% (S\$)	620.55	360.50	260.05	41.91
Nett Amount (S\$)	9,485.59	5,510.50	3,975.09	41.91
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		5,870.50		
Global Sum Settlement (S\$)		5,870.00		

INSPECTION

Date of Assignment:	12/08/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	12/08/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,176.00 FL	*1,176.00 FL
2	1		*REAR BOOT LOCK	Jammed	194.00 FL	*194.00 FL
3	1		*REAR BOOT W/STRIP	Torn	172.00 FL	*172.00 FL
4	1		*REAR BOOT LOGO	Necessary	75.80 FL	*52.00 FL
5	1		*REAR BOOT (SKYACTIM)	Necessary	64.30 FL	*58.30 FL
6	1		*REAR BOOT EMBLEM AXELA	Necessary	78.60 FL	*46.50 FL
7	1		*REAR BUMPER	Broken	974.80 FL	*974.80 FL
8	2		*REAR BUMPER RETAINER L+R	Necessary	84.20 FL	*84.20 FL
9	2		*REAR BUMPER REFLECTOR L+R	Broken	176.40 FL	*176.40 FL
10	2		*REAR BUMPER NUMBER PLATE LAMP L+R	Not Damaged	148.20 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Dented	782.10 FL	*541.70 FL
12	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
13	1		*REAR END PANEL	Dented	747.00 FL	*623.70 FL
14	1		*REAR END PANEL TOP GARNISH	Broken	239.00 FL	*125.00 FL
15	2		*REAR END PANEL CLIP L+R	Necessary	10.00 FL	*10.00 FL
16	1		*REAR END PANEL SENSOR	Scratched	275.00 FL	*253.00 FL
17	2		*TOWING COVER	Necessary (1 PCS ONLY)	155.60 FL	*34.00 FL
18	2		*TAIL LIGHT R/L	Broken	756.60 FL	*756.60 FL
19	2		*REAR BOOT LIGHT R/L	Broken	682.80 FL	*682.80 FL
20	1		*REAR END PANEL TOP GARNISH	Repeated	186.40 FL	*- FL
21	2		*REAR END PANEL TOP GARNISH CLIP	Necessary	15.00 FL	*15.00 FL
22	2		*REVERSE SENSOR	Scratched	560.00 FS	*200.00 FS
23	1		*REAR NUMBER PLATE	Not Damaged	50.00 FS	*- FS
24	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,733.80	6,206.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,408.76	1,201.20
Total Parts (\$\$)	6,325.04	5,004.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS .TO CUT/WELD ,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,000.00	500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	60.00	0.00
4	TO R&R REAR BOOT MECHANISM	New	100.00	80.00
5	TO R&R UPHOSTERY GARNISH AND ATTACHMENT PARTS	New	100.00	0.00
6	TO R&R REVERSE SENSOR AND CHECK FUNCTION	New	80.00	60.00
Gross Labour Cost (\$\$)			2,540.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >