10/6/21, 1:38 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008430/GQF3N2

06/10/2021 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800147116 **Claimant Vehicle** 

SKW3557P Insured Vehicle No: SGG6668P No:

Date of Loss: 11/08/2021 Nature of Claim: ΤP Claim No: 6307970930SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKW3557P

HONDA VEZEL, 1.5 (A) Make & Model: L15B4022754 **Engine No:** Reg. Date: Chassis No: 27/10/2015 (Man. Year: 2015) RU11102745 Colour: Odometer: 150680 km Red

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 12/08/2021

Sau Hock Motor Services (HQ)

10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Date Inspected: 17/08/2021 Inspected At: Autopoint

Singapore 568047

Estimated Period of Repair: 4.0 days

XING GUO QIANG Adjuster: SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$45,000.00 (EST)

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Cut	0.00 F	*- F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1	*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
4	1	*REAR END PANEL	Repair	0.00 F	*- F
5	1	*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
6	1	*TAILGATE	Repair	0.00 F	*- F
7	1	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	2	*TAILGATE LAMP	Broken	0.00 F	*- F
9	1	*TAILGATE RUBBER	Twisted	0.00 F	*- F
г-гіа	anchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	uring this print-out.		

Adjuster Report

10/6/21, 1:38 PM

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >