

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21008432/KUF3N2**Date:** 19/08/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC20P00207400
Claimant Vehicle No :	SKT1461K	Insured Vehicle No :	SGX9014S
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	DMPC2100258H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT1461K	Engine No:	1ZRX513608
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104533748
Reg. Date:	26/05/2015 (Man. Year: 2015)	Odometer:	185114 km
Colour:	Metallic Pearl White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,933.10	2,937.91	1,995.19	40.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,500.00	1,040.00	40.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,473.10	4,437.91	3,035.19	40.61
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	7,473.10	3,550.00	3,923.10	52.50

INSPECTION

Date of Assignment:	12/08/2021	Guan Motor Works (HQ)
Date Inspected:	12/08/2021	Inspected At: 176 Sin Ming Drive #02-03 Sin Ming Autocare
Estimated Period of Repair:	5.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT1461K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	664.20 FL	*581.90 FL
2	2		*REAR BUMPER REFLECTOR	Serviceable	138.40 FL	*- FL
3	2		*REAR BUMPER REVERSE SENSOR	Shorted/Cracked	415.20 FL	*415.20 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Distorted	132.20 FL	*132.20 FL
6	1		*REAR BUMPER INNER REINFORCEMENT	Bent	397.10 FL	*397.10 FL
7	1		*TAILLAMP	O/s Mtg Cracked	783.80 FL	*391.90 FL
8	1		*REAR BOOT LID	Buckled	736.35 FL	*736.35 FL
9	1		*REAR BOOT CENTRE TOYOTA LOGO	Necessary	45.10 FL	*45.10 FL
10	1		*REAR BOOT RH COROLLA EMBLEM	Necessary	65.00 FL	*65.00 FL
11	1		*REAR BOOT RH ALTIS EMBLEM	Necessary	66.20 FL	*66.20 FL
12	1		*SET REAR BOOT INNER TRIM CLIPS	Not Necessary	50.00 FL	*- FL
13	1		*REAR BOOT TOP LOCK	Dented	355.10 FL	*318.10 FL
14	1		*REAR BOOT LOWER LOCK CATCH	Repair	40.00 FL	*- FL
15	1		*REAR END PANEL	Bent	562.10 FL	*562.10 FL
16	1		*REAR END PANEL TOP GARNISH	Serviceable	239.00 FL	*- FL
17	1		*REAR SPARE TYRE TOP BOARD	Serviceable	462.45 FL	*- FL
18	1		*REAR LOWER EXHAUST SILENCER	Repair	971.10 FL	*- FL
19	2		*REAR LOWER EXHAUST SILENCER MOUNTING	Serviceable	98.40 FL	*- FL
20	1		*REAR BOOT WEATHERSTRIP (50%)	Cut	141.83 FS	*94.55 FS
21	1		*SET REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
22	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,498.53	3,875.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,565.43	937.79
Total Parts (\$\$)	4,933.10	2,937.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT,PANEL BEATING,CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	1,000.00	660.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	30.00	20.00
4	TO REMOVE,REFIT REVERSE SENSORS & REVERSE CAMERA	New	150.00	50.00
5	TO REMOVE,REFIT REAR UPHOLSTERY AND ATTACHMENTS	New	120.00	60.00
6	TO REMOVE,REFIT REAR BOOT FITTINGS	New	80.00	50.00
7	TO REMOVE,REFIT REAR EXHAUST SILENCER	New	80.00	0.00
8	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,540.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >