

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG21008438/AUF3N2**Date:** 18/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900009824-02
<b>Claimant Vehicle No :</b>	SMH3385Z	<b>Insured Vehicle No :</b>	SJR81C
Date of Loss:	09/08/2021	Nature of Claim:	TP
		Claim No:	9429135367SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMH3385Z</b>		
Make & Model:	BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	B8540614N20B20B
Reg. Date:	29/04/2014 (Man. Year: 2013)	Chassis No:	WBA5A320X0D334379
Colour:	Black	Odometer:	109744 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,047.26	4,573.80	3,473.46	43.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	860.00	1,360.00	61.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,267.26</b>	<b>5,433.80</b>	<b>4,833.46</b>	<b>47.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,267.26</b>	<b>4,350.00</b>	<b>5,917.26</b>	<b>57.63</b>

INSPECTION

Date of Assignment:	12/08/2021	Unimotor Company - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) Singapore 417883
Date Inspected:	12/08/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FACE	Deformed	1,943.00 FL	*1,515.00 FL
2	1		*FRONT R/H BUMPER SIDE RETAINER	Not Necessary	89.00 FL	*- FL
3	1		*FRONT R/H BUMPER FOG LAMP COVER GARNISH	Cut	278.00 FL	*95.00 FL
4	1		*FRONT R/H HEADLAMP ASSY	Cracked	4,856.00 FL	*3,200.00 FL
5	1		*FRONT R/H HEADLAMP LOWER GARNISH	Not Necessary	133.40 FL	*- FL
6	1		*FRONT R/H FENDER ASSY	Repair	1,350.00 FL	*- FL
7	1		*FRONT R/H FENDER INNER SHIELD	Torn	242.00 FL	*242.00 FL
8	10		*FRONT R/H FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,941.40	5,082.00
- List Item Discount on L Items 10.00/10.00% (\$)	894.14	508.20
Total Parts (\$)	8,047.26	4,573.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISM/REWIRE FRONT DAMAGED PORTION	New	100.00	30.00
2	TO RESET ECU AFTER REPAIR	New	120.00	0.00
3	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	900.00	400.00
4	TO SEND VEHICLE FOR WHEEL ALIGHTMENT	New	120.00	0.00
5	TO PUTTY AND RESPRAY DAMAGED PORTION	New	900.00	400.00
6	TO SPRAY UNDERCOATING IN REPAIR	New	80.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,220.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >