

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008440/AVCE2**Date:** 26/09/2022**REFERENCE**

Insured/Claimant:	KHAW BAN LEONG VICTOR	Policy No:	1700049423-03
Date of Loss:	07/08/2021	Nature of Claim:	OD
		Claim No:	9617435744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8328E		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ512265
Reg. Date:	12/09/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V5J1012901
Colour:	White	Odometer:	0 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,403.00	32,015.60	24,387.40	43.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,564.00	14,047.00	14,517.00	50.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	84,967.00	46,062.60	38,904.40	45.79
Approved Total (Overridden) (\$\$)		43,000.00		
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	84,367.00	42,400.00	41,967.00	49.74
+ GST 7.00/7.00% (\$\$)	5,905.69	2,968.00	2,937.69	49.74
Nett Amount (\$\$)	90,272.69	45,368.00	44,904.69	49.74

INSPECTION

Date of Assignment:	12/08/2021	
Date Inspected:	11/08/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	16.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION LH	Damaged	39.00 FS	*30.48 FS
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	297.00 FS	*- FS
7	1		*FRONT BUMPER TRIM LH	Cut	163.00 FS	*130.00 FS
8	1		*FRONT BUMPER ADAPTAP LH	Damaged	38.00 FS	*29.84 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Missing	188.00 FS	*150.00 FS
10	1		*FOAM FILLER PIECE	Not Necessary	189.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	122.00 FS	*- FS
13	1		*FRONT SIGNAL HORN LH	Not Necessary	200.00 FS	*- FS
14	1		*FRONT FENDER LH	Distorted	851.00 FS	*680.40 FS
15	5		*FRONT FENDER RIVET	Necessary	17.00 FS	*13.20 FS
16	1		*FRONT FENDER ATTACHMENT PART LH	Not Necessary	72.00 FS	*- FS
17	1		*FRONT FENDER BRACE LH	Bent	96.00 FS	*76.48 FS
18	1		*FRONT FENDER BRACKET LH	Bent	39.00 FS	*30.72 FS
19	1		*FRONT FENDER BRACKET LH	Bent	28.00 FS	*21.84 FS
20	1		*FRONT WHEEL HOUSING LINER SEAL LH	Not Necessary	34.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING INSULATION LH	Not Necessary	43.00 FS	*- FS
22	1		*FRONT FENDER CLOSING ELEMENT LH	Not Necessary	33.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER LH	Torn	169.00 FS	*134.80 FS
24	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
25	1		*FRONT PLENUM CHAMBER COVER CENTER	Not Necessary	179.00 FS	*- FS
26	1		*LED HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
27	1		*LED HEAT SINK - LH	Not Necessary	733.00 FS	*- FS
28	1		*LED HEADLIGHT POWER MODULE	Not Necessary	758.00 FS	*- FS
29	1		*LED HEADLIGHT CONTROL UNIT - LH	Not Necessary	557.00 FS	*- FS
30	1		*LIFT CYLINDER - LH	Not Necessary	142.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE - LH	Not Necessary	68.00 FS	*- FS
32	1		*HEADLIGHT WASHER PUMP	Not Necessary	155.00 FS	*- FS
33	1		*WINDSCREEN WASHER PUMP	Not Necessary	125.00 FS	*- FS
34	1		*WINDSCREEN WASHER RESERVOIR	Deformed	206.00 FS	*164.40 FS
35	1		*LOCK CARRIER	Not Necessary	727.00 FS	*- FS
36	1		*RADIATOR COOLANT (6PCS)	Necessary	142.00 FS	*113.60 FS
37	1		*RADIATOR AIR GUIDE - LH	Not Necessary	25.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
39	1		*FRONT DOOR LH	Dented	3,039.00 FS	*2,431.20 FS
40	1		*FRONT DOOR OUTER SEAL LH	Necessary	161.00 FS	*128.40 FS
41	1		*BONDING AGENT LH	Not Necessary	49.00 FS	*- FS
42	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
43	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
44	1		*FRONT DOOR ATTACHMENT PARTS LH	Not Necessary	241.00 FS	*- FS
45	1		*FRONT DOOR CATCH LH	Damaged	105.00 FS	*84.00 FS
46	1		*WATER DEFLECTOR LH	Not Necessary	93.00 FS	*- FS
47	1		*WINDOW CHROME SLOT SEAL - LH	Cut	309.00 FS	*246.80 FS
48	1		*WINDOW CHROME TRIM STRIP - LH	Not Necessary	257.00 FS	*- FS
49	1		*FRONT FENDER LOWER MOUNTING BRACKET LH	Not Necessary	65.00 FS	*- FS
50	1		*FRONT FENDER CLOSING ELEMENT LOWER CENTER	Not Necessary	74.00 FS	*- FS
51	1		*FRONT FENDER LOWER MOUNTING RIVET	Not Necessary	12.00 FS	*- FS
52	1		*FRONT SUSPENSION FRAME	Cut	1,000.00 FS	*800.00 FS
53	1		*SET FRONT SUSPENSION FRAME BUSHES	Necessary	112.00 FS	*89.20 FS
54	1		*FRONT LOWER ARM LH	Bent	373.00 FS	*298.00 FS
55	1		*FRONT STABILIZER BAR	Bent	395.00 FS	*316.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT WHEEL BEARING HOUSING LH	Damaged	579.00 FS	*462.80 FS
57	1		*FRONT WHEEL HUB LH	Damaged	478.00 FS	*382.40 FS
58	1		*FRONT LOWER ARM BALL JOINT LH	Damaged	124.00 FS	*98.80 FS
59	1		*FRONT COUPLING ROD	Bent	99.00 FS	*77.76 FS
60	1		*FRONT DRIVE SHAFT LH	Damaged	2,211.00 FS	*1,768.80 FS
61	1		*FRONT GAS SHOCK ABSORBER LH	Bent	259.00 FS	*206.80 FS
62	1		*FRONT TIE ROD LH	Bent	92.00 FS	*73.04 FS
63	1		*FRONT TIE ROD END LH	Bent	122.00 FS	*97.20 FS
64	1		*STEERING GEAR	Not Necessary	4,964.00 FS	*- FS
65	1		*STEERING GEAR KIT	Not Necessary	43.00 FS	*- FS
66	1		*ARCYLIX SEALANT	Not Necessary	180.00 FS	*- FS
67	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
68	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
69	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
70	1		*FRONT LHS RIM	Cut	1,166.00 FS	*1,166.00 FS
71	1		*SUNDRIES	Necessary	450.00 FS	*189.76 FS
72	1		*FRONT PLENUM CHAMBER COVER LH	Not Necessary	41.00 FS	*- FS
73	1		*FRONT ABSORBER TOP MOUNTING - LH (Supplementary)	Damaged	122.00 FS	*97.20 FS
74	1		*FRONT ABSORBER TOP MOUNTING BEARING - LH (Supplementary)	Damaged	46.00 FS	*36.16 FS
75	1		*FRONT ABSORBER DUST COVER - LH (Supplementary)	Not Necessary	54.00 FS	*- FS
76	1		*FRONT ABSORBER COIL SPRING - LH (Supplementary)	Not Necessary	248.00 FS	*- FS
77	1		*FRONT BRAKE DISC COVER - LH (Supplementary)	Bent	48.00 FS	*37.84 FS
78	1		*FRONT BRAKE CALIPER HOUSING - LH (Supplementary)	Not Necessary	446.00 FS	*- FS
79	1		*FRONT BRAKE CALIPER MOUNTING - LH (Supplementary)	Not Necessary	288.00 FS	*- FS
80	1		*FRONT BRAKE PAD (Supplementary)	Not Necessary	211.00 FS	*- FS
81	1		*FRONT BRAKE DISC (Supplementary)	Cut	165.00 FS	*131.60 FS
82	5		*BOLTS - BRAKE HOUSING (Supplementary)	Not Necessary	30.00 FS	*- FS
83	1		*FRONT BRAKE HOSE RETAINER - LH (Supplementary)	Not Necessary	10.00 FS	*- FS
84	2		*FRONT BRAKE HOSE BRACKET - LH - LH (Supplementary)	Damaged	5.00 FS	*3.52 FS
85	1		*NOISE INSULATION - ENGINE COVER (Supplementary)	Cracked	290.00 FS	*232.00 FS
86	12		*BOLTS - NOISE INSULATION (Supplementary)	Necessary	26.00 FS	*20.40 FS
87	1		*DRIVE SHAFT - LH (Supplementary)	Repeated	2,211.00 FS	*- FS
88	7		*DRIVE SHAFT BOLTS (Supplementary)	Necessary	38.00 FS	*29.68 FS
89	1		*GEARBOX (Supplementary)	Cracked	17,519.00 FS	*14,015.20 FS
90	1		*FRONT WHEEL HOUSING LINER - RH (Supplementary)	Cut	169.00 FS	*135.20 FS
91	1		*FRONT LOWER ARM - RH (Supplementary)	Bent	373.00 FS	*298.00 FS
92	1		*RIM RH (NPA) (Supplementary)	Cut	0.00 FS	*- FS
93	1		*FRONT BRAKE HOSE - LH (Supplementary)	Damaged	82.00 FS	*65.04 FS
94	1		*BRAKE HOSE (Supplementary)	Torn	82.00 FS	*65.60 FS
95	1		*RETAINER FOR BRAKE HOSE (Supplementary)	Not Necessary	10.00 FS	*- FS
96	1		*SPEED SENSOR (Supplementary)	Damaged	186.00 FS	*148.40 FS
97	1		*WIRING FOR SPEED SENSOR (Supplementary)	Torn	221.00 FS	*176.80 FS
98	1		*DOUBLE STUD HAXAGON DRIVE (Supplementary)	Damaged	24.00 FS	*19.04 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	9		*MULTI-POINT SOCKET HEAD BOLTS (Supplementary)	Damaged	74.00 FS	*57.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					56,403.00	32,015.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
5	TO TOW BACK THE VEHICLE FROM ACCIDENT SCNE	New	280.00	0.00
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
7	TO REMOVE AND REINSTALL DASHBOARD ASSY TO FACILITATE RENEW OF LHS A-PILLAR INNER PLATE	New	2,400.00	0.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS A-PILLAR INNER PLATE. TO REPAIR LHS FRONT FENDER TOP SUPPORT. LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	7,000.00	1,500.00
9	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR, LHS A-PILLAR INNER PLATE, LHS SILL PANEL AND LHS WING MIRROR COVER	New	6,000.00	1,850.00
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
12	TO REMOVE AND REINSTALL ENGINE ASSY AND GEAR BOX TO FACILITATE RENEWAL OF GEARBOX ASSY. TO CARRY OUT CALIBRATION ADAPTIVE FOR GEARBOX ASSY (Supplementary)	New	2,800.00	2,800.00
13	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER (Supplementary)	New	800.00	800.00
14	TO REPAIR LHS CHASSIS MEMBER AND LHS FRONT WHEEL HOUSING TOP MOUNTING (Supplementary)	New	1,400.00	750.00
15	TO RESPRAY LHS CHASSIS MEMBER AND LHS FRONT WHEEL HOUSING TOP MOUNTING (Supplementary)	New	2,000.00	825.00
Gross Labour Cost (\$)			28,564.00	14,047.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >