

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008441/AUCN2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant: HEUNG TSZ KIN ULYSSES Policy No: 1800153960-01
Date of Loss: 10/08/2021 Nature of Claim: OD Claim No: 3163975666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG5845E**
Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK071121
Reg. Date: 26/12/2018 (Man. Year: 2018) Chassis No: WAUZZZF4XKN000814
Colour: Blue Odometer: 62909 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,531.00	5,381.84	18,149.16	77.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,092.00	3,052.00	9,040.00	74.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,623.00	8,433.84	27,189.16	76.32
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	34,023.00	6,833.84	27,189.16	79.91
+ GST 7.00/7.00% (S\$)	2,381.61	478.37	1,903.24	79.91
Nett Amount (S\$)	36,404.61	7,312.21	29,092.40	79.91

INSPECTION

Date of Assignment: 12/08/2021
Date Inspected: 11/08/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	72.00 FS	*56.32 FS
4	1		*FRONT BUMPER GRILLE CENTER	Deformed	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE LH	Damaged	63.00 FS	*50.08 FS
7	1		*RADIATOR GRILLE	Cracked	1,332.00 FS	*1,065.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	135.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION LH	Damaged	36.00 FS	*28.72 FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*LOCK CARRIER SUPPORT LH/RH	Not Necessary	58.00 FS	*- FS
17	2		*FRONT PARKING AID SENSOR (Npa)	Missing (1 Pc only)	0.00 FS	*- FS
18	1		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*FRONT BUMPER WIRING SET	Not Necessary	510.00 FS	*- FS
20	1		*HORN LH	Not Necessary	12.00 FS	*- FS
21	1		*HORN BRACKET LH	Not Necessary	29.00 FS	*- FS
22	1		*FRONT FENDER LH	Dented	767.00 FS	*613.20 FS
23	1		*FRONT FENDER ATTACHMENT LH	Not Necessary	202.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	72.00 FS	*57.52 FS
25	1		*FRONT FENDER BRACKET LH	Not Necessary	35.00 FS	*- FS
26	1		*FRONT FENDER DEFORMATION ELEMENT	Not Necessary	49.00 FS	*- FS
27	1		*FRONT FENDER BRACKET LH	Not Necessary	32.00 FS	*- FS
28	1		*FRONT FENDER BRACE LH	Bent	118.00 FS	*94.40 FS
29	1		*FRONT WHEEL HOUSING LINER LH	Deformed	240.00 FS	*191.60 FS
30	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER LH	Not Necessary	73.00 FS	*- FS
32	1		*FRONT WHEEL SPOILER TRIM LH	Not Necessary	35.00 FS	*- FS
33	1		*FRONT WHEEL STONE CHIP GUARD LH	Not Necessary	51.00 FS	*- FS
34	1		*FRONT FENDER FLEDGE COVER-LONG	Necessary	31.00 FS	*24.64 FS
35	1		*FRONT FENDER FLEDGE COVER-SHORT	Bent	23.00 FS	*17.92 FS
36	1		*LED HEADLIGHT-LH	Not Necessary	7,693.00 FS	*- FS
37	1		*LIFT CYLINDER-LH	Not Necessary	210.00 FS	*- FS
38	1		*LIFT CYLINDER HOSE-LH	Not Necessary	93.00 FS	*- FS
39	1		*LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
40	1		*LOCK CARRIER LOWER SUPPORT LH	Not Necessary	38.00 FS	*- FS
41	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS
42	1		*RADIATOR AIR GUIDE LH	Not Necessary	28.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE LH	Not Necessary	12.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE CENTER	Not Necessary	16.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE LOWER	Not Necessary	22.00 FS	*- FS
46	1		*FRONT LOWER ARM LH	Not Necessary	539.00 FS	*- FS
47	1		*FRONT SUSPENSION GUIDE LH	Not Necessary	943.00 FS	*- FS
48	1		*FRONT UPPER ARM LH FRONT	Not Necessary	512.00 FS	*- FS
49	1		*FRONT UPPER ARM LH REAR	Not Necessary	512.00 FS	*- FS
50	1		*FRONT WHEEL HOUSING BEARING LH	Not Necessary	968.00 FS	*- FS
51	1		*FRONT LOWER ARM BALL JOINT LH	Not Necessary	193.00 FS	*- FS
52	1		*FRONT WHEEL HUB LH	Not Necessary	479.00 FS	*- FS
53	1		*FRONT WHEEL BEARING LH	Not Necessary	246.00 FS	*- FS
54	1		*FRONT SUSPENSION FORK LH	Not Necessary	264.00 FS	*- FS
55	1		*FRONT COUPLING ROD LH	Not Necessary	167.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT GAS SHOCK ABSORBER	Not Necessary	301.00 FS	*- FS
57	1		*FRONT TIE ROD LH	Not Necessary	99.00 FS	*- FS
58	1		*FRONT TIE ROD END LH	Not Necessary	197.00 FS	*- FS
59	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
60	1		*FRONT LHS TYRE	Cut	0.00 FS	*420.00 FS
61	1		*FRONT LHS RIM	Cut	0.00 FS	*1,100.00 FS
62	1		*SUNDRIES	Necessary	400.00 FS	*15.84 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 23,531.00 5,381.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT,PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.TO RENEW LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	2,400.00	0.00
7	TO RENEW LHS FRONT RIM WITH TYRE.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			12,092.00	3,052.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >