

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21008442/AUF3N2**Date:** 07/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLT1021K	Insured Vehicle No :	SLS9308L
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003421

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1021K		
Make & Model:	TOYOTA COROLLA, 1.5 G AXIO HYBRID (A)	Engine No:	1NZR497971
Reg. Date:	17/10/2017 (Man. Year: 2017)	Chassis No:	NKE1657144644
Colour:	Black	Odometer:	355490 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,487.76	2,807.00	5,680.76	66.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,230.00	420.00	25.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,137.76	4,037.00	6,100.76	60.18
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	10,137.76	3,200.00	6,937.76	68.43
+ GST 7.00/7.00% (S\$)	709.64	224.00	485.64	68.43
Nett Amount (S\$)	10,847.40	3,424.00	7,423.40	68.43

INSPECTION

Date of Assignment:	12/08/2021	
Date Inspected:	12/08/2021	Inspected At: Hua Hong Pte Ltd (HQ) Blk 8 Kaki Bukit Ave 4, #06-31, Singapore 415875 Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Oct 2021)

Parts: 143 TOYOTA COROLLA 1.5 G AXIO HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT1021K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,255.75 FL	*780.00 FL
2	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	602.40 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
4	1		*REAR BOOT	Dented	2,126.75 FL	*821.00 FL
5	1		*REAR BOOT CHROME	Not Necessary	985.50 FL	*- FL
6	1		*REAR BOOT EMBLEM	Necessary	171.60 FL	*75.00 FL
7	1		*REAR BOOT LOGO (COROLLA)	Necessary	122.70 FL	*58.00 FL
8	1		*REAR BOOT LOGO (AXIO)	Necessary	136.80 FL	*55.00 FL
9	1		*REAR TAIL LAMP (LH)	Cracked	1,704.90 FL	*458.00 FL
10	1		*REAR END PANEL	Dented	1,740.75 FL	*682.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	691.80 FL	*166.00 FL
12	1		*NUMBER PLATE	Not Necessary	35.00 FS	*- FS
13	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
14	1		*REAR BOOT LOGO (HYBRID)	Necessary	136.80 FL	*60.00 FL
15	1		*REAR BOOT WEATHERSTRIP	Cut	321.70 FL	*187.00 FL
16	1		*REAR BOOT LOCK	Damaged	268.50 FL	*104.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,550.95	3,676.00
- List Item Discount on L Items 20.00/25.00% (\$)	2,063.19	869.00
Total Parts (\$)	8,487.76	2,807.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD REAR END PANEL.TO CHANGE REAR BUMPER,REAR BOOT KNOCKING ALL AREA AFFECTED BY ACCIDENT	New	800.00	600.00
2	TO PERFORM WIRING CHECK	New	50.00	30.00
3	TO SPRAY REAR END PANEL,REAR BUMPER,REAR BOOT AND ALL AFFECTED AREA	New	800.00	600.00
Gross Labour Cost (\$\$)			1,650.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >