

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008446/EQCN2**Date:** 30/08/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00186742000	
Claimant Vehicle No :	SMR6926R	Insured Vehicle No :	SMW7115G	
Date of Loss:	06/08/2021	Nature of Claim:	TP	Claim No: SNM21D204407/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6926R		Engine No:	44135874B38A15A
Make & Model:	BMW 216I, 1.5 ACTIVE TOURER (A)		Chassis No:	WBA2X920407F37158
Reg. Date:	17/01/2020 (Man. Year: 2019)		Odometer:	23207 km
Colour:	Blue			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,223.10	3,002.75	4,220.35	58.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,537.00	4,712.00	1,825.00	27.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,760.10	7,714.75	6,045.35	43.93
+ GST 7.00/7.00% (\$\$)	963.21	540.03	423.18	43.93
Nett Amount (\$\$)	14,723.31	8,254.78	6,468.53	43.93

INSPECTION

Date of Assignment:	12/08/2021	Performance Motors Limited (Alexandra)
Date Inspected:	17/08/2021 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)

Parts: 143 BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR6926R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID	Dented	1,216.40 FS	*1,216.40 FS
2	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	161.15 FS	*- FS
3	1		*REAR BUMPER CARRIER	Not Necessary	483.40 FS	*- FS
4	1		*SUPPORT	Not Necessary	45.75 FS	*- FS
5	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	161.15 FS	*- FS
6	1		*LH PROTECTION FOIL	Not Necessary	5.65 FS	*- FS
7	1		*RH PROTECTION FOIL	Not Necessary	5.65 FS	*- FS
8	1		*REAR BUMPER TRIM STRIP (BLACK)	Broken	88.20 FS	*88.20 FS
9	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Dented	1,050.65 FS	*1,050.65 FS
10	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	61.00 FS	*- FS
11	1		*LETTERING 216I	Necessary	64.75 FS	*64.75 FS
12	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
13	1		*PLAQUE 74MM	Necessary	71.95 FS	*71.95 FS
14	1		*STRIKER BOOT LID	Not Necessary	60.10 FS	*- FS
15	1		*LOCK TRUNK LID	Not Necessary	195.75 FS	*- FS
16	10		*BUMP STOP	Necessary	32.00 FS	*32.00 FS
17	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	43.25 FS	*- FS
18	1		*REAR WINDOW ESG	Not Necessary	657.60 FS	*- FS
19	1		*TRUNK LID SEALING	Not Necessary	97.85 FS	*- FS
20	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	376.30 FS	*- FS
21	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	263.40 FS	*- FS
22	1		*RH GUTTER STRIP	Not Necessary	53.30 FS	*- FS
23	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.60 FS	*- FS
24	4		*ULTRASONIC SENSOR IMPERIAL BLAU (WA89)	Not Necessary	1,484.80 FS	*- FS
25	1		*SET ADHESIVE PADS FOR ACE 2.0	Not Necessary	43.65 FS	*- FS
26	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
27	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
28	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
29	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
30	3		*BLIND RIVET NUT M6	Necessary	8.10 FS	*8.10 FS
31	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,223.10** **3,002.75**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER,REAR BOOT LID INCLUDE REMOVE ATTACHMENT ETC	New	2,125.00	1,700.00
2	PAINTING REAR BOOT LID,REAR TAIL PANEL AND REAR BUMPER	New	2,666.00	1,826.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT,CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	257.00
7	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
Gross Labour Cost (\$)			6,537.00	4,712.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >