

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008447/AUCN2**Date:** 08/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00088902101		
Claimant Vehicle No :	SKU7741H	Insured Vehicle No :	GBG4155A		
Date of Loss:	10/08/2021	Nature of Claim:	TP	Claim No:	SNM21D204443/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU7741H		
Make & Model:	KIA CERATO FORTE, 1.6 KOUP SX (M)	Engine No:	G4FC9H340710
Reg. Date:	07/01/2010 (Man. Year: 2009)	Chassis No:	KNAFW611LA5174366
Colour:	Black	Odometer:	133054 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,691.42	8,664.56	9,026.86	51.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	2,840.00	3,350.00	54.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,881.42	11,504.56	12,376.86	51.83
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	23,881.42	9,200.00	14,681.42	61.48
+ GST 7.00/7.00% (S\$)	1,671.70	644.00	1,027.70	61.48
Nett Amount (S\$)	25,553.12	9,844.00	15,709.12	61.48

INSPECTION

Date of Assignment:	12/08/2021		
Date Inspected:	12/08/2021	Inspected At:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Sep 2021)

Parts: 143 KIA CERATO FORTE 1.6 KOUP SX (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU7741H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Not Necessary	145.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINERS	Necessary	117.20 FL	*117.20 FL
3	2		*FRONT BUMPER FOG LAMP	Not Necessary	451.20 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP BRACKET	Not Necessary	170.00 FL	*- FL
5	1		*FRONT SUPPORT PANEL	Cracked	542.30 FL	*542.30 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	538.60 FL	*- FL
7	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	136.80 FL	*- FL
8	1		*HEADLAMP ASSY	O/s Cracked	1,191.60 FL	*595.80 FL
9	1		*HEADLAMP BRACKETS	O/s Cracked	181.20 FL	*90.60 FL
10	1		*BOOTLID	Buckled	896.80 FL	*896.80 FL
11	2		*BOOTLID HINGES	Not Necessary	157.00 FL	*- FL
12	2		*BOOTLID LAMPS	Cut	890.60 FL	*650.00 FL
13	2		*BOOTLID LAMPS INNER SEALS	Necessary	80.00 FL	*40.00 FL
14	2		*BOOTLID NUMBER PLATE LAMPS	Not Necessary	116.00 FL	*- FL
15	1		*BOOTLID LOCK	Damaged	185.80 FL	*185.80 FL
16	1		*BOOTLID LATCH	Not Necessary	48.00 FL	*- FL
17	1		*BOOTLID INSULATOR	Not Necessary	235.60 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP	Cut	185.90 FL	*185.90 FL
19	1		*REAR BUMPER	Distorted	705.20 FL	*705.20 FL
20	1		*REAR BUMPER LOWER	Deformed	328.60 FL	*328.60 FL
21	1		*REAR BUMPER REFLECTOR	N/s Cut	159.40 FL	*79.70 FL
22	2		*REAR BUMPER MUDFLAP	Not Necessary	116.00 FL	*- FL
23	2		*REAR BUMPER SIDE RETAINERS	Necessary	96.00 FL	*96.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Cracked	378.10 FL	*378.10 FL
25	1		*REAR BUMPER REINFORCEMENT SPONGE	Cracked	195.60 FL	*195.60 FL
26	1		*SMART KEY ANTENNA	Not Necessary	165.00 FL	*- FL
27	1		*END PANEL	Dented	450.40 FL	*450.40 FL
28	1		*END PANEL TOP GARNISH	Deformed	154.80 FL	*154.80 FL
29	1		*SPARE TYRE PANEL	Repair	652.60 FL	*- FL
30	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	335.70 FL	*- FL
31	2		*TAILLAMPS	N/s Cut/O/s Cracked	875.60 FL	*875.60 FL
32	2		*TAILLAMP INNER SEALS	Necessary	80.00 FL	*20.00 FL
33	2		*TAILLAMP BRACKETS	Not Necessary	170.00 FL	*- FL
34	2		*TAILLAMP PANELS	Repair	451.20 FL	*- FL
35	1		*EXHAUST PIPE	Not Necessary	1,800.00 FL	*- FL
36	4		*EXHAUST PIPE MUFFLER	Not Necessary	340.00 FL	*- FL
37	1		*FRONT BONNET-CARBON FIBER	Deformed	1,860.00 FS	*1,000.00 FS
38	1		*FRONT BONNET STAND CLIP	Not Necessary	35.00 FS	*- FS
39	1		*FRONT NUMBER PLATE W CASING	Not Necessary	70.00 FS	*- FS
40	1		*FRONT BUMPER-FIBER	Deformed	1,450.00 FS	*800.00 FS
41	1		*FRONT BUMPER LOWER GRILLE-UPPER CENTER	Not Necessary	60.00 FS	*- FS
42	1		*FRONT BUMPER LOWER GRILLE-LOWER CENTER	Not Necessary	120.00 FS	*- FS
43	2		*FRONT BUMPER LOWER GRILLE-SIDE	Not Necessary	120.00 FS	*- FS
44	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
46	1		*REAR BOOTLID SPOILER	Cracked	350.00 FS	*350.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BOOTLID LOGO	Necessary	135.00 FS	*65.00 FS
48	1		*REAR BOOTLID EMBLEM-KOUP	Necessary	60.00 FS	*60.00 FS
49	1		*REAR BOOTLID DECAL-HOONIGAN	Necessary	120.00 FS	*50.00 FS
50	1		*REAR NUMBER PLATE W CASING	Deformed	70.00 FS	*70.00 FS
51	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
52	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
53	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
54	1		*END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
55	1		*SPARE TYRE PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS
56	2		*TAILLAMP CLIPS	Necessary	70.00 FS	*10.00 FS
57	2		*REAR FENDER INNER TRIM CLIPS-2 SET	Not Necessary	60.00 FS	*- FS
58	2		*REAR FENDER INNER COWLING CLIPS-2 SET	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,063.80	9,323.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,372.38	658.84
Total Parts (\$\$)	17,691.42	8,664.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT/STRAIGHTEN/REALIGN ACCIDENT AFFECTED AREAS	New	2,500.00	1,400.00
2	TO SPRAY PAINTS AFFECTED AREAS	New	2,500.00	1,000.00
3	TO TUFF COAT AFFECTED AREAS	New	200.00	60.00
4	TO CHECK AND REALIGN HEADLAMP FOCUS	New	60.00	30.00
5	TO DISMANTLE,REPLACE AND/OR REPAIR AIR CON CONDENSER & REFILL AIR CON GAS	New	150.00	60.00
6	TO DISMANTLE,REPLACE AND/OR REPAIR RADIATOR AND PRESSURE TEST	New	150.00	60.00
7	TO CONDUCT WIRING/WIRE CONNECTOR CHECK AND REPAIR	New	60.00	60.00
8	TO DISMANTLE/TRANSFER BOOTLID COMPONENTS	New	150.00	60.00
9	TO REMOVE/REFIX INTERIOR UPHOLSTERY,ROOF LINING,SEATS,SAFETY BELT,SPEAKER BOARD EG	New	120.00	60.00
10	TO REFIX/STRAIGHTEN REAR EXHAUST PIPE	New	150.00	0.00
11	TO REMOVE/REFIX REVERSE SENSORS AND DISTANCE SETTING	New	150.00	50.00
Gross Labour Cost (\$\$)			6,190.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >