

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008450/KES3Q2**Date:** 28/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079444-03
Claimant Vehicle No : SMG2733P **Insured Vehicle No :** SMC5193Z
 Date of Loss: 28/07/2021 Nature of Claim: TP Claim No: 7430233817SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG2733P**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR6884745
 Reg. Date: 12/12/2018 (Man. Year: 2016) Chassis No: ZVW506051591
 Colour: Metallic Grey Odometer: 260446 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Sailun 3 mm Rear Left Side: Sailun 8 mm
 Front Right Side: Sailun 3 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,141.66	907.09	1,234.57	57.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	535.00	1,115.00	67.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,791.66	1,442.09	2,349.57	61.97
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	3,791.66	1,150.00	2,641.66	69.67
+ GST 7.00/7.00% (S\$)	265.42	80.50	184.92	69.67
Nett Amount (S\$)	4,057.08	1,230.50	2,826.58	69.67
+ Loss of Use (2.0 x S\$70.00/day) (S\$)		140.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,377.95		

INSPECTION

Date of Assignment: 12/08/2021
 Date Inspected: 16/08/2021 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	928.35 FL	*497.50 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	141.40 FL	*141.40 FL
3	1		*REAR BUMPER DIFFUSER	Dented	379.00 FL	*379.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	458.00 FL	*- FL
5	1		*REAR BUMPER LH SIDE LAMP	Serviceable	281.50 FL	*- FL
6	1		*REAR BUMPER LH SIDE GARNISH	Mtg Cracked	381.80 FL	*191.55 FL
7	1		*REAR BUMPER LH SIDE INNER SHIELD	Serviceable	285.50 FL	*- FL
					Sub Total (\$)	2,855.551,209.45
					- List Item Discount on L Items 25.00/25.00% (\$)	713.89302.36
					Total Parts (\$)	2,141.66907.09

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	50.00	15.00
2	SPRAY PAINTING	New	800.00	300.00
3	LABOUR CHARGES	New	800.00	220.00
Gross Labour Cost (\$)			1,650.00	535.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >