

ASS. REC. BY:

REF:

A/G/ 21008450/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 2733P

Yr Regn:

12.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pirus

c.c.

1787

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

260446

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW 50

6051591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailun

Front

R/Bal.

3

mm

Rear

R/Bal.

8

mm

L/Bal.

3

mm

L/Bal.

8

mm

D.O.A.

28/7/21

D.O.I.

16/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/8 11PM @ 1150/ Continued

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Paints

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

28/07/2021

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG2733P

1pc	rear bumper	497.50	mgcm	\$	928.35	✓
1pc	rear bumper LH side retainer		D.I	\$	141.40	✓
1pc	rear bumper diffuser		mc	\$	379.00	✓
1pc	rear bumper reinforcement		R	\$	458.00	X
1pc	rear bumper LH side lamp		sm	\$	281.50	X
1pc	rear bumper LH side garnish	191.55	mgcm	\$	381.80	✓
1pc	rear bumper LH side inner shield		sm	\$	285.50	X
					\$ 2,855.55	
less 25%					\$ 713.89	
					\$ 2,141.66	

wiring	\$	50.00	15h
spray painting	\$	800.00	300d
labour charges	\$	800.00	220d
Total	\$	3,791.66	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



16/08/21
Monday
after 11am
LKK

Not within
11pm @ 1150h
2 days
Return after pain