

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008451/KES3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMK3343D**Insured Vehicle No :** SMC6692T

Date of Loss: 09/08/2021

Nature of Claim:

TP

Claim No: 6906623181SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK3343D**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU126552

Reg. Date: 05/04/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU893763

Colour: Metallic Dark Blue

Odometer: 30566 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Kumho 7 mm

Rear Left Side: Kumho 7 mm

Front Right Side: Kumho 7 mm

Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,212.12	923.72	1,288.40	58.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	510.00	990.00	66.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,712.12	1,433.72	2,278.40	61.38
+ GST 7.00/7.00% (S\$)	259.85	100.36	159.49	61.38
Nett Amount (S\$)	3,971.97	1,534.08	2,437.89	61.38
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,656.08		

INSPECTION

Date of Assignment: 12/08/2021

Date Inspected: 18/08/2021 Inspected At:

Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT EMBLEM W HANDLE	Serviceable	196.20 FL	*- FL
2	1		*REAR BOOT AVANTE LOGO	Not Necessary	31.20 FL	*- FL
3	1		*REAR BOOT S LOGO	Not Necessary	55.00 FL	*- FL
4	1		*REAR BOOT LOCK	Repair	116.20 FL	*- FL
5	1		*REAR BUMPER	Buckled	459.40 FL	*459.40 FL
6	1		*REAR BUMPER LOWER GARNISH	Mtg Cracked	353.50 FL	*353.50 FL
7	1		*REAR BUMPER LAMP LH	Serviceable	201.50 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	26.10 FL	*- FL
9	10		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
10	1		*REAR BUMPER NO PLATE GARNISH	Dented	28.00 FL	*28.00 FL
11	2		*REAR BUMPER NO PLATE LAMP LH & RH	Serviceable	56.00 FL	*- FL
12	1		*REAR BUMPER BEAM	Repair	294.80 FL	*- FL
13	1		*REAR BUMPER STAY LH	Serviceable	78.60 FL	*- FL
14	1		*REAR BUMPER STAY RH(NPA)	Serviceable	0.00 FL	*- FL
15	1		*REAR END PANEL	Repair	454.60 FL	*- FL
16	1		*REAR END PANEL GARNISH	Serviceable	59.80 FL	*- FL
17	1		*SMART KEY ANTENNA ASSY	Serviceable	40.50 FL	*- FL
18	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
19	1		*NUMBER PLATE (OPC)	Bent	35.00 FS	*35.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,706.40	1,095.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					494.28	172.18
Total Parts (\$\$)					2,212.12	923.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
2	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
3	TO ARRANGE ,SUPPLY AND SEAL OF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY	New	60.00	60.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
5	TO DISMANTE ALL DAMAGED PARTS .TO CUT & WELD REAR END PANEL TO KNOCK & REPAIR REAR BOOT ,SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	200.00
6	TO SPRAY REAR BOOT ,REAR BUMPER ,REAR END PANEL	New	600.00	200.00
Gross Labour Cost (\$\$)			1,500.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >