



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108517

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/12/2021
Reference CC4/FCI21008454/T1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMK 7280A
Insured Veh. SBS 6302R
Claim No. D21002286MFBP/1
Policy No. D-21097502MFBP
Accident Date 09/08/2021
Inspection Date 12/08/2021

Description	Total
Survey Inspection	390.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	390.00
GST (7%)	27.30
Grand Total	417.30

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008454/T1ra3q2	
			Date: 10/12/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6302R	Veh. Inspected	SMK 7280A	
Policy No.	D-21097502MFBP	Coverage (\$)	0.00	
Claim No.	D21002286MFBP/1	Excess (\$)	0.00	
Assign From	MERINA	Assign Date	11/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MMBSTA13AKH001400	Colour	SILVER	
Odometer	106631 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	GITI	6 mm	
L/H Front Tyre	185/55 R15	GITI	6 mm	
R/H Rear Tyre	185/55 R15	GITI	6 mm	
L/H Rear Tyre	185/55 R15	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/08/2021	Inspection Date	12/08/2021	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 7280A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	687.20	687.20
2	FRONT BUMPER RETAINER	N/S NOT NECESSARY / O/S NECESSARY	56.40	28.20
1	FRONT BUMPER FOG LAMP	CRACKED	189.60	189.60
1	FRONT BUMPER FOG LAMP COVER	CUT	89.20	89.20
1	FRONT BUMPER FOG LAMP CHROME	CUT	138.50	138.50
1	FRONT BUMPER INNER GARNISH	NOT NECESSARY	186.65	-
1	FRONT BUMPER REINFORCEMENT	BENT	387.90	350.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	168.00	168.00
1	FRONT GRILLE	NOT NECESSARY	322.80	-
1	FRONT GRILLE OUTER CHROME MOULDING	NOT NECESSARY	246.60	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	87.00	-
1	FRONT FENDER RH	BENT	438.90	438.90
1	FRONT FENDER INNER SHIELD RH	TORN	181.40	181.40
1	FRONT FENDER EMBLEM	NECESSARY	59.00	59.00
1	FRONT FENDER INNER PANEL	NOT NECESSARY	469.90	-
1	FRONT FENDER BRACKET RH	NOT NECESSARY	52.25	-
1	WASHER TANK	DEFORMED	89.20	89.20
1	HEADLAM RH	CRACKED	576.00	510.00
1	BONNET	TO REPAIR SEE LABOUR	722.00	-
2	BONNET HINGE	NOT NECESSARY	183.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	268.00	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	344.70	-
1	FRONT KNUCKLE ARM RH	BENT	438.00	329.00
1	FRONT KNUCKLE ARM BEARING RH	BENT	389.60	282.00
	LESS 10% DISCOUNT		-677.18	-354.02
			6,094.62	3,186.18
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	10.00
1	BRAKE FLUID (SN)	NOT NECESSARY	50.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	250.00	-
1	FRONT RIM (SN)	CUT	400.00	400.00
			760.00	440.00
	LABOUR			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	COMPUTERISED AND CHECK WHEEL ALIGNMENT.		200.00	80.00
	REMOVE AND REPLACE FRONT UNDERCARRIAGE.		200.00	100.00
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF BONNET .		1,200.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	500.00
	APPLY ANTI RUST ON AFFECTED AREAS .		150.00	30.00
			3,010.00	1,140.00
GRAND TOTAL			9,864.62	4,766.18

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
---	--	--	-----------------

Report Ref No. CC4/FCI21008454/T1ra3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 7280A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 7280A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 7280A

RE-INSPECTION

